

JUL 11 2014

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name CHAPARRAL ENERGY LLC	API Number 30-025-12262 ✓
Property Name West DOLLARhide Queen SAND UNIT	Well No. 9 ✓

7. Surface Location

UL - Lot	Section 30	Township 24-5	Range 38-E	Feet from 2310	N/S Line FNL	Feet From 2310	E/W Line FEL	County Lea
----------	----------------------	-------------------------	----------------------	--------------------------	------------------------	--------------------------	------------------------	----------------------

Well Status

Well Status	SHUT-IN	PRODUCING ✓	DATE 6-25-14
-------------	---------	----------------	------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	0			0	1100
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	<input checked="" type="radio"/> Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

DID A Pressure TEST ON CASING.

Signature: William Dunlap	OIL CONSERVATION DIVISION
Printed name: William Dunlap	Entered into RBDMS
Title: Prod. Tech	Re-test
E-mail Address: William.Dunlap@chaparralenergy.com	
Date:	Phone: 432-561-9462
Witness:	

AUG 22 2014