Submit One Copy To Appropriate District State of New Mexico	Form C-103
District 1 1625 N. French Dr., Hobbs, NM 88240 Energy, Minerals and Natural Resources	Revised August 1, 2011 WELL API NO. 30-025-26526
District II 811 S. First St., Grand Ave., Artesia, NM 82140 OIL CONSERVATION DIVISION	5. Indicate Type of Lease
882101220 South St. Francis Dr.District IIISanta Fe, NM 87505	6. State Oil & Gas Lease No.
District IV	
1220 S. St. Francis Dr., Santa Fc, NM 87505	B-2181
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name East Vacuum GB-SA Unit T ract 2648
1. Type of Well: XOil Well Gas Well Other	8. Well Number 01
2. Name of Operator ConocoPhillips Company	9. OGRID Number 217817
3. Address of Operator P. O. Box 51810 Midland, TX 79710 RECEIVED	10. Pool name or Wildcat Vacuum; GB-SA
4. Well Location	
Unit Letter <u>N</u> : <u>1310</u> feet from the <u>South</u> line and <u>1380</u> feet from the <u>West</u> line Section <u>26</u> Township <u>175</u> Range <u>35E</u> NMPM <u>County Lea</u>	
Interview Interview	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
I PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT	
OTHER: 🗌 🛛 Location is re	eady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the 	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment. X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)	
X All other environmental concerns have been addressed as per OCD rules.	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. retrieved flow lines and pipelines.	All fluids have been removed from non-
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
when an work the been completed, remained form to the appropriate District office to schedule an inspection.	
SIGNATURE ton Staff Regulatory Tech	DATE 06/02/2014
TYPE OR PRINT NAME <u>Rhonda Rogers</u> E-MAIL: <u>rogerrs@conocopl</u> For State Use Only Image: Conocopl	
APPROVED BY: Mach Lethitchen TITLE Compliance	AUG 29 2014 PM
Conditions of Approval (if any):	ALLE 20 DOLL FM - LIN