Submit One Copy To Appropriate District Office	State of New Mexico		Form C-103 Revised November 3, 2011
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-24984 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE FEE
District IV	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			N/A
(DO NOT HER THE FORM FOR PRODOG	ES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC	ALS TO DRILL OR TO DEEPEN OR PLANTION FOR PERMIT" (FORM C-101) FO	OR SUCHARS ACA	West Knowles
PROPOSALS.) 1. Type of Well: Oil Well			8. Well Number 4
2. Name of Operator		OCT 2 2 2014	9. OGRID Number
Hunt Cimarron Limited Partnership 3. Address of Operator	/		164726 10. Pool name or Wildcat
P.O. Box 1592, Roswell, NM 88202		RECEIVED	Knowles; Drinkard, West
4. Well Location		15 Wites Tot 2018 VI (2019	
Unit Letter B: 660 feet from the North line and 1,980 feet from the East line			
Section <u>34</u> Township <u>16S</u> Range <u>37E</u> NMPM <u>Lea</u> County <u>NM</u>			
II. Elevation (Show whether DR, RKB, RT, GR, etc.) 3775' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	PLUG AND ABANDON	REMEDIAL WORK	
		CASING/CEMENT	
OTHER:		☐ ☐ Location is re	ady for OCD inspection after P&A
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 			
 Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 			
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.) All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE Cahe CAULO TITLE: Vice President DATE: 10/20/2014			
SIGNATURE Cahe Hall TITLE: Vice President DATE: 10/20/2014			
TYPE OR PRINT NAME: Richard C. Gilliland E-MAIL: richard.gilliland@huntcompanies.com PHONE: (575) 623-9799			
For State Use Only			
APPROVED BY: Mall	Kitchen TITLE (jonghance	Officer DATE 10/21/2014
		1	Officer DATE 10/21/2014 OCT 2 3 2014

fb