
Submit 1 Copy To Appropriate District	ice State of New Mexico				Form C-103		
District 1 – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources			ELL API NO.	Revised July 18, 2013		
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			025-05306 Indicate Type of Le	ease		
District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	1220 South St. Francis Dr. Santa Fe, NM 87505			STATE State Oil & Gas Lea	FEE 🖂		
1220 S. St. Francis Dr., Santa Fe, NM 87505					ase no.		
SUNDRY NOT	ICES AND REPORTS	FEPEN OR PLUG BACK T		Lease Name or Uni	t Agreement Name		
DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)	CATION FOR PERMIT" (FO	DRM C-101) FOBBS OC	Der Der	nton SWD			
1. Type of Well: Oil Well 2. Name of Operator	Gas Well 🛛 Other			Well Number 3			
Fasken Oil and Ranch, Ltd.		OCT 222	151	416			
3. Address of Operator 6101 Holiday Hill Road, Midland,	TX 79707	RECEIVE		Pool name or Wild D; Wolfcamp-Pen/			
4. Well Location	330		<u>I</u>				
Unit Letter <u>M</u> Section 12	feet from the <u>-660</u> . Township	e <u>South</u> line ar 15S Range	nd <u>330'</u> 37E	feet from the NMPM	<u>West</u> line County Lea		
	11. Elevation (Show	whether DR, RKB, RT,			eounty Lea		
	3576' GR						
12. Check	Appropriate Box to	Indicate Nature of	Notice, Repo	ort or Other Dat	a		
						r	
PERFORM REMEDIAL WORK	PLUG AND ABANDO CHANGE PLANS		AL WORK		ERING CASING		
PULL OR ALTER CASING	MULTIPLE COMPL		CEMENT JOB				
CLOSED-LOOP SYSTEM		OTHER:	Repair Cs	g. Leak & return to	Inj. 🛛		
 Describe proposed or comp of starting any proposed we 							
proposed completion or rec	completion. S. Nor	Maryly G. B	NUCH, (103 Accef			
7-11-14 – 8-30-14	ildea		Chart	· bill Jon	nation can	./	
MIRU. RU Renegade Wireline, I	تی تی RIW/ w/ 2 81" blanking	the Original	Vietan rat 9335' RU	reverse unit on a	- q q q z 0 q z d z		
seated plug w/ 350 psi. Sheared	l off blanking plug, PC)W, RD Renegade W	Vireline, press	sure tested plug to	o 1000 psi f/ 30" on	Ű.	
chart recorder w/ no loss of press loaded well w/ 3 bbw (FL 518'), t	ested packer and plug	g to 1500 psi f/ 15" w	/ no loss of pr	ressure. Release	ed packer, POW to		
9190', set packer, tested old squ reverse unit, pressure tested cas							
Wolfcamp squeeze f/ 9220' - 932 attachment for additional information	25' w/ packer set at 91						
Spud Date:	Rig	g Release Date:					
		L					
I hereby certify that the information	above is true and comp	lete to the best of my k	knowledge and	belief.			
SIGNATURE / Jun Jun	TI	TLE <u>Regulat</u>	ory Analyst	DATE	10-20-2014		
Type or print name Kim Ty For State Use Only	<u>eson</u> E-	mail address: <u>k</u>	imt@forl.com_	PHONE:	432-687-1777		
APPROVED BY: <u>Silver</u> Conditions of Approval (if any):	and TI	TLE_Staff	Nanbger	DATE_	4105/42/01		
						~	
				OCT 272	014 fr W		



CWB/SRF 10/24/14 Fasken Oil Ranch, Ltd. CWB Printed 10/24/2014 Denton SWD_3_WBD.xls

OCT 22 2014

RECEIVED

Fasken Oil and Ranch, Ltd. Denton SWD No. 3/ API No. 30-025-05306 Repair Casing Leak & Return to Injection Sundry Notice Attachment

7-11-14 - 8-30-14

POW w/ 2-7/8" tubing while isolating casing leak in 7" casing and isolated leak f/ 5122' - 5154'. RU reverse unit on tubing and tried to get injection rate into leak at 1/4 bpm without success. With 1/2 bbw pumped, well pressured up to 1050 psi, observed pressure bled off 200 psi in 15". Pressured back up on leak several times w/ same results. Note: While packer set at 4621', 26' inside 7" liner, loaded 9-5/8" casing w/ 10 bbw (FL 144'), tested 9-5/8" casing and liner top to 500 psi for 10" with a loss of 80 psi, possible leak indicated in 9-5/8" casing. Had problems with tools used to test casing. Note: Capitan Wireline set to run casing inspection log 7-23-14. RU Capitan Wireline, RIW w/ 60 arm Multi-Sensor Caliper Log w/ MT tool, tagged top of RBP at 9336', opened tool and logged well from 9336' to top of 7" liner at 4596'. Closed tool, POW and RD Capitan Wireline. Observed casing to have light to medium pits w/ a possible hole in collar 5140'. Attempted to set RBP at different intervals without success. RBP became stuck and was finally pulled free. RIW w/ RBP retrieving tool, 4' x 2-7/8" tubing sub, 7" HD packer w/ 6.0" gauge rings, 2-7/8" seating nipple, 164 joints 2-7/8" tubing and set packer at 5154'. RU reverse unit on tubing and pressured 7" casing to RBP set at 9325' to 500 psi w/ a loss of 5 psi in 5" and released packer. POW to 5122', RU reverse unit on tubing, pressure tested 7" casing to RBP at 500 psi for 10" with a loss of 10 psi. RU reverse unit on 9-5/8" casing, loaded well w/ 1/2 bbw, pressure tested casing to surface at 500 psi for 5" with a loss of 60 psi. Released packer, POW to 5091', set packer, RU reverse unit on tubing, pressure tested to RBP w/ 500 psi f/ 10" w/ a loss of 10 psi. Released packer, POW to 4621, 26' from TOL at 4595', set packer, RU reverse unit on tubing and tested to RBP at 500 psi f/ 25" with a loss of 15 psi, contacted Midland office w/ results, all testing recorded with chart recorder. Released packer, POW and LD 7" packer. ND 11" spool and BOP, RIW w/ 9-5/8" 32A tension packer and 2 joints 2-7/8" tubing, NU 11" spool and BOP, finished RIW w/ 70 joints 2-7/8" tubing to 2218' and set packer. RU reverse unit on tubing, tested casing to RBP to 500 psi for 15" w/ a loss of 5 psi. RU reverse unit on 9-5/8" casing, loaded well w/ 6.7 bbw (FL-96' FS), packer at 2218' FS and pressure tested to surface to 500 psi w/ 40 psi loss in pressure 2". Released packer, isolated hole in 9-5/8" casing from 967-998', pressure tested casing from 967' to surface to 500 psi f/ 15" with a loss of 5 psi. RIW to 1093', set packer, pressure tested casing to RBP to 500 psi f/ 35" w/ 10 psi loss. Released packer, POW, ND 11" spool and BOP and stood packer in derrick, RIW w/ 9-5/8" Arrowset I w/ equalization valve, 1 joint 2-7/8" tubing, NU 11" spool and BOP, finished RIW w/ 55 joints 2-7/8" tubing to 1748', 750' below bottom of hole at 998', set RBP, disengaged retrieving tool, POW and LD retrieving tool. ND 11" spool and BOP, RIW w/ 9-5/8" 32A tension packer w/ 9.50' FG sub tailpipe, 2-7/8" seating nipple, 2 joints 2-7/8" tubing, NU 11" spool and BOP, finished RIW w/ 54 joints 2-7/8" tubing to 1719' and set packer. RU reverse unit on tubing, tested RBP to 2000 psi f/ 10" with no loss of pressure, released packer, spotted 550#, 12.6', 20/40 sand on top of RBP, POW w/ 9-5/8" packer to 840', 127' above top of hole at 967', left packer swinging, SWI and SDON. POW w/ 2 joints 2-7/8" tubing to 778' w/ EOT at 787', set packer and tested to 500 psi, closed casing valve bled pressure off and observed valve leaking, replaced valve and trapped 500 psi on casing. Squeeze hole in 9 5/8" casing from 967' - 998' w/ 250 sx class "C" + 2% CaCl2 (s.w. 14.8 ppg, yield 1.33 cuft/sk). Well SI, WOC. Tagged TOC @ 828', drilled cement from 828'-973'. Fell out of good cement and drilled stringers to 985' and circulated well clean. Pressure tested casing to 440 psi f/ 10" w/ no loss of pressure. Tested to 460 psi on chart

recorder f/ 40" with 5 psi increase in pressure and contacted Midland office w/ results. Tagged top of sand at 1739'. Established reverse circulation, washed sand off RBP at 1748' and circulated well clean. POW with RBP. NU 11" spool and BOP, RIW w/ 7" retrieving tool to 9315', RU reverse unit on casing, installed TIW valve on tubing, pressured casing to 450 psi f/ 10" w/ no loss of pressure, RU chart recorder, charted 410 psi f/ 35" w/ a loss of 5 psi, bled pressure off, contacted Midland office w/ results. RIW w/ 1 joint 2-7/8" tubing, tagged 9320', 5' fill on RBP, RU swivel and reverse unit, established reverse circulation, washed fill off RBP and engaged retrieving tool, observed dirty heavy fluid w/ a lot of fine flakey scale, circulated well clean w/ 170 bbw and released RBP. Called for slick OD and ID Texas pattern shoe. Note: Contractor filled frac tank w/ 10# brine water, Endura delivered 220 gals CI 811 and mixed in frac tank. RIW with a total 298 joints 2-7/8" tubing and 5-1/2" smooth OD shoe, tagged at 9335', RU tubing swivel. established reverse circulation, washed to top of injection packer at 9337', top of profile nipple 9336', circulated bottoms up w/ 55 bbw and observed pieces cement, casing, scale and formation. Circulated well clean w/ a total of 320 bbw while working 5-1/2" shoe f/ 9327' - 9337'. POW to 9308' and SD f/ 1 hour. RIW and tagged at 9337', no fill, circulated bottoms up w/ 55 bbw and observed little scale and formation. LD tubing swivel, POW and LD 195 joints 2-7/8" workstring to 3345'. SWI and SDON. Finished POW and LD a total of 302 joints 2-7/8" tubing and 5-1/2" Texas pattern shoe, ND BOP and 11" spool and NU wellhead. Contractor cleaned and jetted reverse pit. Cleaned location and hung barriers around wellhead. RDPU and left on location. Well SI, waiting on injection tubing. RIW w/ 215 jts. - 4-1/2" 11.60# J-55 IC101 IPC tubing @ 9347' w/ packer @ 9335'. RU pump truck on casing, pressured casing to 500 psi f/ 30" with no loss of pressure and bled pressure off. NDWH and 11" spool, NU 11" tubing hanger. landed hanger w/ 20K compression on packer, NUWH and tested to 1000 psi. Note: Contacted NMOCD, Maxey Brown of notice to run MIT test on 9-4-14 at 8:15 a.m. MST on 9-3-14. RU M&S Service pump truck on casing loaded well w/ 1/2 bbw tested casing to 410 psi for 34" with a loss of 10 psi. Test was witnessed and signed off on by Bill Sonnamaker with the NMOCD, bled pressure off and RD pump truck. RU disposal flowline to wellhead, RDPU and cleaned location.