<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720

State of New Mexico Energy, Minerals and Natural Resources Department

HOBBS OCD

OCT 1 6 2014

OCT 3 0 2014

	UII CO	nservation	DIVISION HO	iods D	Istrict	Office		RECEIV	 IE R	
BRADENHEAD TEST REPORT										
Operator Name							API Number			
Seely Oil Company Property Name							30-025-37587			
EKQUEED							1019			
		⁷ Si	Irface Location	on					······································	
UL - Lot Section Township Range . Feet from								E/W Line	j County	
N 13 18	<u>35 33E</u>		<u>330</u>		<u>;</u>	93	101	W.	Lea_	
		, I	Vell Status							
TA'D WELL	SHUT-IN INJECTOR			PRODUCER					DATE)	
YES NO	YES	NO (INJ)	SWD	OIL		GAS	(101	1/2014	
									- SADIOCU	
		<u>OBS</u>	ERVED DA	ATA						
	-							•	\frown	
	(A)Surface	(B)Interm(1)		(C)Interm(2)			(D)Prod Csng		(E)Tubing	
ressure	0					0		1900		
low Characteristics										
Puff	Y/N	Y/N		Y/N			Y/N			
Steady Flow	Y/N	Y/N		¥7 N		Y/N		WTR X GAS		
Surges	Y/N	Ý / N		Y/N		Y/N		Type of Fluid		
Down to nothing	Y/N	Y / N		Y/N		Y/N		Injected for		
Gas or Oil	Y/N	Y/N		Y/N		Y7 N		Waterflood if applies.		
Water	Y7 N	Y/	N		Y/N		Y	7 N	1 .	
				·			L			
			•							
emarks – Please state for eac	h string (A,B,C,D,E) pert	inent information	regarding bleed	down or	continuo	us build up	if applies.			
				,						
	FOR	RECOR	JUNIT							

BS 10/17/2014 Signature 11 OIL CONSERVATION DIVISION Printed name: Shellie Davis Entered into RBDMS Re-test Title: Production Analyst . E-mail Address: sdavis@seelyoil.com Date: 10/10/2014 Phone: 817-332-1377 engran Witness: