	HOBBSOUP			
(DO NOT USE THIS FORM FOR PROPOSAL DIFFERENT RESERVOIR. USE "APPLICAT PROPOSALS.) 1. Type of Well: X Oil Well ☐ Ga.	State of New Me Energy, Minerals and Natural OIL CONSERVATION 1220 South St. Fran Santa Fe, NM 87 S AND REPORTS ON WELLS S TO DRILL OR TO DEEPEN OR PLUTION FOR PERMIT" (FORM C-101) FOR	xico 06 2 ral Resources DIVISIONECEIVE 1505 JG BACK TO A 15 SUCH	WELL API NO. 30-025-39523 5. Indicate Type STATE 6. State Oil & Ga B-9680 7. Lease Name o Red Raider 3 Stat 8. Well Number	X FEE as Lease No. r Unit Agreement Name ae 1H
2. Name of Operator Manzano, LLC		i i	9. OGRID Numb 231429	er
3. Address of Operator PO Box 2107 Roswell, NM 88202			10. Pool name or Tulk; Wolfcamp	Wildcat
4. Well Location Unit Letter A: 660 feet from the North line and 175 feet from the East line Section 3 Township 15S Range 32E NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4293 GR 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING COMMENCE DRILLING OPNS. P AND A X PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB OTHER: Location is ready for OCD inspection after P&A				
UNIT LETTER, SECTION,	and leveled. Cathodic protectio	n holes have been provel has been set in convel has been proved by the been proved has been proved by the been set in converted by the been set in been set in converted by the been set in been set i	operly abandoned oncrete. It shows	the ER LOCATION OR
 X The location has been leveled as near other production equipment. X Anchors, dead men, tie downs and r X If this is a one-well lease or last rem OCD rules and the terms of the Operato from lease and well location. X All metal bolts and other materials has to be removed.) 	risers have been cut off at least twaining well on lease, the battery or's pit permit and closure plan.	wo feet below ground and pit location(s) ha All flow lines, produce	level. ave been remediat ction equipment a	ed in compliance with nd junk have been removed

Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-

X If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well

E-MAIL: ___john.worrall@senmgeologist.com ___ PHONE: __

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

All other environmental concerns have been addressed as per OCD rules.

John Worrall

retrieved flow lines and pipelines.

location, except for utility's distribution infrastructure.



Manzano, LLC

P.O. Box 2107 Roswell, New Mexico 88202-2107 (575) 623-1996 FAX (575) 625-2620

November 19, 2014

HOBBS OCD

NOV 2 0 2014

Lea County Electric Cooperative, Inc. P.O. Drawer 1447 Lovington, NM 88260

RECEIVED

Re:

Red Raider 3 State #1H 660' FNL and 175' FEL, Section 3, T15S-R32E Lea County, New Mexico

30-025-39523

Gentlemen:

Please remove the stub pole and transformers on the above referenced location for the Red Raider 3 State #1H. Let me know if you have any questions or comments in this regard.

Sincerely,

Debbi Jeffers

cc: Hobbs OCD Office