NOV 2 4 2014

Submit One Copy To Appropriate District	State of New Me	xico	F	orm C-103
Office District I	Energy, Minerals and Natu		/FD Revised Nov	ember 3, 2011
1625 N. French Dr., Hobbs, NM 88240		Mr.	WELL API NO.: 30-025-2404	7
District II 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
District III	1220 South St. Francis Dr.		STATE S FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 8750	•			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			North Vacuum ABO West Uni	it _
PROPOSALS.)			8. Well Number: 016	
1. Type of Well: Oil Well Gas Well Other: Injection				
2. Name of Operator: Chevron, USA INC.		9. OGRID Number: 4323		
3. Address of Operator: 15 Smith Road, Midland, TX 79705			10. Poòl name or Wildcat	
· · · · · · · · · · · · · · · · · · ·			Vacuum; ABO, North (Oil & Gas)	
4. Well Location: Unit Letter: F 1980 feet from the North line and 1980 feet from the West line Section: 28 Township 178 Range				
34E NMPM County Lea				
3.	11. Elevation (Show whether DR,	RKB, RT, GR, etc.)	: 9999	
12. Check Appropriate Box	to Indicate Nature of Notice, Ro	eport or Other Da	ıta	
NOTICE OF I	NTENTION TO:	SUBS	SEQUENT REPORT OF	;.
PERFORM REMEDIAL WORK		REMEDIAL WORK		CASING
TEMPORARILY ABANDON	<u> </u>		<del></del> -	
PULL OR ALTER CASING		CASING/CEMENT	JOB 🖾	_/
OTHER:	] .		ady for OCD inspection after l	P&A
	in compliance with OCD rules and the			n.
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAI	MPED ON THE MARKER'S SUR	FACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)  All other environmental concerns have been addressed as per OCD rules.				
<ul> <li>➢ An other chylrotimental concerns have been addressed as per Oeb rules.</li> <li>➢ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-</li> </ul>				
retrieved flow lines and pipelines.				
	st remaining well on lease: all electric	cal service poles and	lines have been removed from	lease and well
location, except for utility's distrib	ution infrastructure.			
		N	. 1. 1	
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE:	2//	C	DATE: 11/04/14	
SIGNATURE: YPI	7/TITLE:	Construction Rep	DATE: <u>11/24/14</u>	
TYPE OR PRINT NAME:Jon	Ruff E-MAIL: iruff	@chevron.com	PHONE: 916-708-8248	
For State Use Only		/ / / / / / / / / / / / / / / / / / / /		
M <sub>1</sub>	1.411	)	Aller is	12/2011
APPROVED BY: \(\sigma\)	Whatalam TITLE C	unpronce c	1771cer DATE 12	1 312UY
Londitions of Approval (if any).				