HOBBS OCD

Submit One Copy To Appropriate District State of New Mex Office	Form C-103
<u>District I</u> Energy, Minerals and Natur	al Resources Revised November 3, 2011 WELL API NO. 30-025-12388
1625 N. French Dr., Hobbs, NM 88240 District II	DECEIVED
811 S. First St., Artesia, NM 88210 OIL CONSERVATION	DIVISION 5. Indicate Type of Lease
District III 1220 South St. France 1000 Pio Progres Pd. Agree NM 87410	CIS Dr. STATE OF P. Con Longo No.
District IV Santa Fe, NM 875	6. State Off & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOI	
PROPOSALS.) 1. Type of Well: Oil Gas Other	8. Well Number: 024
2. Name of Operator: Chevron, USA INC	9. OGRID Number: 4323
3. Address of Operator: 15 Smith Road, Midland, TX 79705	10. Pool name or Wildcat
	Dollarhide; Fusselman (Oil & Gas)
4. Well Location: Unit Letter <u>B:816</u> feet from the <u>North</u> line and <u>1780</u> feet from the <u>East</u> line Section <u>05</u> Township 2 <u>5S</u> Range <u>38E</u> NMPM County <u>Lea</u>	
11. Elevation (Show whether DR, RKB, RT, GR, etc.): 3158	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR	
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
☑ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least to	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	in now inited, production equipment and junit nave even removed
All metal bolts and other materials have been removed. Portable bas	es have been removed. (Poured onsite concrete bases do not have
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non- 	
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well	
location, except for utility's distribution infrastructure.	all service poles and lines have been removed from lease and wen
When all work has been completed, return this form to the appropriate District office to schedule an inspection.	
SIGNATURE TITLE: Construction Rep DATE 10/30/14 1/24/14	
TYPE OR PRINT NAME: Jon Ruff_ E-MAIL: jruff@chevron.com PHONE: 916-708-8248	
For State Use Onlys	
APPROVED BY: Wal Whitzler TITLE Compliance Officer DATE 12/8/2014	
Conditions of Approval (if any):	

Z,~