Submit 1 Copy To Appropriate District	State of New M	exico	Form C-103		
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011		
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.		
<u>District'</u> √ (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-33403 5. Indicate Type of Lease		
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 8	7505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM	•		o. State on & Gas Bease 110.		
87505	CIOCO AND DEDODTE ON WELL	C	7. I am Name at Italy Assessment Name		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PROPOSALS TO DRILL OR TO DEEP NOTICE TO DEE			7. Lease Name or Unit Agreement Name WEST DOLLARHIDE DRINKARD		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			UNIT		
PROPOSALS.)			8. Well Number 155		
1. Type of Well: Oil Well Gas Well Other Injector DEC 18 2014			9. OGRID Number 4323		
2. Name of Operator CHEVRON U.S.A. INC.			9. OGRID Number 4323		
3. Address of Operator		RECEIVED	10. Pool name or Wildcat		
15 SMITH ROAD, MIDLAND T	EXAS 79705		Dollarhide; Drinkard		
4. Well Location					
	2000 feet from the South line	and 2550 fee	t from the East line		
<u> </u>					
Section 32	Township 24S Range 11. Elevation (Show whether DI				
	11. Elevation (Snow whether Di	N, KKD, KI, GK, etc.,			
ly <u>alayaan daadala sasaan daa daa daa daa daa daa daa daa daa </u>	ــــــــــــــــــــــــــــــــــــــ		Francis atomic conservations are also manufactured a Arabic second		
12 Charle	Ammonista Day to Indicate I	Notice of Notice	Damant on Other Data		
12. Check	Appropriate Box to Indicate N	valure of Notice,	Report of Other Data		
NOTICE OF I	NTENTION TO:	SUB	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK		REMEDIAL WOR	_		
TEMPORARILY ABANDON		COMMENCE DRI			
PULL OR ALTER CASING		CASING/CEMEN	_		
DOWNHOLE COMMINGLE	-		_		
OTHER:			, acidize & return to injection		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or re	completion.				
Please find the attached report for a	work performed on the subject well	on 10/21/14			
Please find the attached report for work performed on the subject well on 10/21/14. Also attached is the wellbore diagram.					
· 					
	D: D 1 T	. .			
Spud Date:	Rig Release I	pate:			
			11.1.6		
I hereby certify that the informatio	n above is true and complete to the	best of my knowledg	ge and belief.		
<i>h</i> - 1	1				
SIGNATURE OLA-HOLAN	1 / or to 2 TITLE PE	RMIT SPECIALIST	DATE 11/10/2014		
ordinarion of the state of the			51112 1111012011		
Type or print name Britany Cor	tez E-mail address:	Bcortez@chevron	.com PHONE: 432-687-7415		
For State Use Only					
		.	10/10/11		
APPROVED BY:	TITLE	Petroleum Engin	DATE / 1/8/19		
Conditions of Approval (if any):					

WDDU #155 Location: 2000 FSL, 2550 FEL, Sec. 32, Township S024, Range E038, Lea Co., NM TEAM: Dollarhide FMT DATE CHKD: Aug. 01, 2014 FIELD: Dollarhide (WDDU) BY: J. Daraie LEASE/UNIT: West Dollarhide Drinkard Unit WELL: WDDU #155 COUNTY: Lea STATE: **New Mexico** SPUD DATE: 7/19/1996 KB = +13'COMP. DATE: 8/26/1996 Elevation = 3192' GL TD = 7250' CTI: 10/15/2004 CURRENT STATUS: FTD = 6471Injector (water) PBTD = 6471' API = 30-025-33403 CHEVNO = BJ4795 Perf 6663'-7125' w/2 JSPF, 132 holes. Acdz w/10,000 gals 20% HCL. 6446'-6576', w/2 JSPF, 86 holes. Acdz w/6500 gals 20% HCL. 11" Subsequent Workover or Reconditioning: hole 1-4-99 MIRU, POH w/105 rods, parted on 7/8" coupling. TIH w/ fishing tool and caught fish. Tag @ 7193' - no fill. Set CIBP @ 6740'. TIH w/sonic hammer tool, & tbg & wtr wash & acdz perfs w/1200 gals 15% NEFE. Drop ball & Swab. TIH w/202 jts 2-7/8" L80 tbg, TAC, 10 jts 2-7/8" L80, SN 2-7/8" x 3-1/2" mud jt. TAC set w/15 pts @ 6386' & SN @ 6703'. TIH w/2-1/2" x 1-1/4" pmp w/1-1/2" x 10' gas anchor, 9 - 1-3/4" sinker bars, 103 3/4" D87 rods, 79 7/8" D87 rods, 74 1" D87 rods. Changed out 56 3/4" couplings, 23 7/8" cplgs & 5 -1" cplgs. Space out 7" off bottom & load & Test. Rig dn. OPT 11 Oil, 33 Wtr, 8 MCF, GOR 727. Scale sqz w/1 drum TH 793. 04-02-01: Tubing failure 10-15-04: Conversion - Producer to Injector. Cleanout w/ sonic hammer, acid wash perfs w. 4000 gallons 15% anti-sludge HCl. 8-5/8" 24# unknown type csg, set @ 1190' w/ 525 sx cmt circ. to surface. Description Top Depth Bottom Depth Quantity Lenath Tubing count not accurate. Tubing, 2-7/8" J-55, IPC 203.00 6394.50 13.00 6407.50 No accurate record Tubing Sub, 2-7/8" J-55, IPC 6407.50 6411.50 available. 7-7/8" Packer set @ 6362' (Arrowset 1X w/ on/off tool & 1.50" SS 'F' profile) Perf. Drinkard: 6446-48', 6453-55', 59-66', 69-73', 77-83, 86-88, 93-95, 6504-16', 32-36, 74-76 w/ 2 JDPF - 180 Deg phasing - 86 holes (43 net ft of perfs) CIBP set @ 6655' w/ 35' cmt on top CIBP set @ 6740' Perf. Abo: 6663'-70', 6678'-81', 6689'-92', '6696'-6700', 6747'-51', 6770'-78', 6783'-86', 6827'-29', 6848'-52' 6868'-71', 6884'-87', 6980'-82', 6996'-7002', 7028'-31', 7103'-10', 7121'-7125' w/ 2 JDPF, 90 deg phasing 132 holes (66 net ft of perfs) 5-1/2" 15.5# & 17# L80 LTC & WC50 csg, set @ 7250' w/ 1820 sx circ to surface TD 7250

PRTD 67401



Summary Report

Major Rig Work Over (MRWO)

Stimulation

Job Start Date: 10/20/2014 Job End Date: 10/20/2014

Well Name	Lease	Field Name	Business Unit
WEST DOLLARHIDE DRINKARD	West Dollarhide Drinkard Unit	Dollarhide - Primary	Mid-Continent
UNIT 056			
Ground Elevation (ft) Original RKB (ft)	Current RKB Elevation		Mud Line Elevation (ft) Water Depth (ft)

Report Start Date: 10/20/2014

Com

JSA REVIEW TO MOVE IN AND SPOT COIL TBG UNIT, CRANE, ACID TRUCK AND EMERGENCY SHOWER TRAILER STATION.

RU 1.25" COIL TBG UNIT AND EQUIPMENT OVER WELL AND SECURE

PERFORMED COIL TBG JSA REVIEW AND WTJSA. POINTED OUT RESTRICTED AREAS, LINE OF FIRE, EQUIPMENT, CHEMICALS AND COMMUNICATED JOB PROCEDURE. ESTABLISHED A MUSTARD POINT AND ASSIGNED A DESIGNATED HOSPITAL WITH EMERGENCY NUMBERS POSTED.

PRESSURE TESTED COIL TUBING @6,000 PSI FOR 10 MINUTES "HELD" BLED OFF PRESSURE.

CUT OFF COIL TUBING BULL PLUG AND INSTALL THE FOLLOWING BHA;

5" x 1 1/4" ROLL ON CONNECTOR

4' x 1 1/4" STRAIGHT BAR

1 1/4" DUAL CHECK VALVES

8" x 1 1/4" SONIC HAMMER

FUNCTION TEST BOP / TESTED BOP AGAINST GATE VALVE TO 300 PSI LOW"HELD FOR 10 MINUTES & 3,000 PSI HIGH"HELD" 10 MINUTES, TESTED DUAL CHECK VALVE FOR 10 MINUTES @ 2,500 PSI "HELD" / BLED OFF ALL PRESSURES.

NOTE

COMMUNICATED TO ME BY CUDD FIELD SUPERVISOR THAT IT IS NOT RECOMMENDED TO PULL TEST AGAINST A ROLL ON CONNECTOR BECAUSE IT MIGHT DAMAGE THE ROLL ON SEALS.

MADE SURE GOOD CIRCULATION WAS ESTABLISHED THROUGH ALL EQUIPMENT AND NO RESTRICTIONS WERE ENCOUNTERED.

WELL TBG PRESSURE WAS 1,650 PSI. RIH WITH 8" x 1.25 SONIC HAMMER > 1-4' x 1.25" STRAIGHT BARS > 2' x 1.25" DUAL FLAPPER CHECK VALVE ON 1.25 COIL TBG / RIH FROM SURFACE TO 6,755" WHILE CIRCULATING. WE DID NOT TAG HARD FILL BUT DID SEE A QUICK WEIGHT CHANGE AROUND 6,584'. WE ATTEMPTED TO WORK PAST 6,755' BUT WERE UNSUCCESSFUL. CONSTANT WEIGHT CHECKS WERE MADE EVERY 500'-1,000' THROUGHOUT THIS PHASE.

- 1. AVERAGE SPEED TO PACKER= 65 FPM
- 2. AVERAGE BPM PUMPED= .25
- 3. UNDER PACKER ASPM= 16'
- 4. UNDER PACKER ABPM= 1.00
- 5. WHILE RIH THE AVERAGE RETURN RATE WERE 1/2 BPM @ 1,000 PSI.
- 6.WHILE WASHING PERFS WITH FRESH WATER AND CIRCULATING OUT THE RETURN RATE WAS 2 1/2 BPM @40 PSI

PERFORMED 2 SWEEPS ACROSS PERF'S WITH FRESH WATER @ 2 BPM @ 4,750 PSI CTP/ CIRCULATED CLEAN WITH 35 BBL'S FROM 6,755' TO SURFACE.

SHUT IN ANNULUS AND BULLHEAD PERF'S WITH 6,000 GAL OF 15% HCL IN 17 SWEEPS FROM 6,607 UP 6,481'. AVERAGE BACK SIDE PRESSURE WAS 1,000 PSI. PUMP RATE WAS .75 BPM / ON PASS #16 WE TAGGED @ 6,558', ATTEMPTED TO GO THROUGH BUT WITH NO SUCCESS.

NOTE

FILL WAS TAGGED WITH SLICKLINE ON 7/2014 @6,584'

WE CLEANED OUT TO 6,755' GIVING YOU 148' OF RATHOLE.

RETURNS RECOVERED AT SURFACE WERE SCALE LIKE MATERIAL- IRON SULFIDE

OVER DISPLACED BY 5 BBL'S TO REMOVE ACID FROM COIL TBG / WHEN PACKER WAS REACHED WE THEN POOH WITH 1.25 COIL TBG & BHA WHILE ANNULUS REMAINED SHUT IN.

CT WAS CLEANED WITH FRESH WATER TO REMOVE ACID / SODA ASH WILL BE USED AFTER NEXT WELL (PER CUDD FIELD SUPERVISOR RECOMMENDATIONS)

DEBRIEF WITH CREW MEMBERS ON A JOB WELL DONE.

RD COIL TBG AND EQUIPMENT FROM WELL.

WELL HAD 1,450 PSI / FLOWED BACK FOR 1 HR AND RECOVERED 195 BBL'S (SAMPLE COLLECTED) SHUT WELL IN WITH 640 PSI

RD FLOW BACK EQUIPMENT FROM WELL.