Submit One Copy To Appropriate District State of New Mexico Office District 1 1625 N. French Dr., Hobbs, NM 88240	Form C-103
Office Energy Minerals and Natural Resources	Revised November 3, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II	30-025-10687
District II 811 S. First St., Artesia, NM 88210 District III 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 8/410 Conto Eq. NIM 97505	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. 301940
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name Skelly Penrose B Unit
PROPOSALS.) 1. Type of Well: Gas Well Other - INJECTION	8. Well Number 54
2. Name of Operator	9. OGRID Number
Providence Energy Services, Inc. dba Kelton Operating	012444
3. Address of Operator	10. Pool name or Wildcat
P.O. Box 928, Andrews, TX 79714-0928	Langlie Mattix (37240)
4. Well Location	
Unit Letter L : 1980 feet from the SOUTH line and 66	feet from the <u>WEST</u> line
Section 9 Township 23-S Range 37-E NMPM	County Lea
11. Elevation (Show whether DR, RKB, RT, GR, etc.	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR	_
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
	/
OTHER:	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	ON HAS BEEN WELDED OR
I BRIMANDIA DI MANIE ED ON THE MANIE O SORT INCES	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location.	
All metal bolts and other materials have been removed. Portable bases have been removed.	oved. (Poured onsite concrete bases do not have
to be removed.)	
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles ar	nd lines have been removed from lease and well
location, except for utility's distribution infrastructure.	۴.
When I and her has a smalleted action this forms to the appropriate District office to go	hadula an inspection
When all work has been completed, return this form to the appropriate District office to sol	nequie an inspection.
TITLE Desident	
SIGNATURETITLE President	DATE <u>12/27/2014</u>
	DATE <u>12/27/2014</u> @suddenlink.net PHONE: 432-661-1364
TYPE OR PRINT NAME C. Dale Kelton E-MAIL: providenceenergy	@suddenlink.net PHONE: 432-661-1364