Submit One Copy To Appropriate District Office State of New Mex	•
District I Energy, Minerals and Natur 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 811 S. First St., Artesia, NM 88210 OIL CONSERVATION	1.5 Indicate Type of Lease
District III 1220 South St. France 1000 Rio Brazos Rd., Aztec, NM 87410 South St. France 1000 Rio Brazos Rd., Aztec, NM 87410 South St. France 1000 Rio Brazos Rd., Aztec, NM 87410	STATE STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUIDIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)	RSUCH
1. Type of Well: Oil Well Gas Well Other	8. Well Number 001
2. Name of Operator LINN OPERATING INC	9. OGRID Number 269324
3. Address of Operator 600 TRAVIS, SUITE 5100, HOUSTON, TX 77002	10. Pool name or Wildcat VACUUM; DEVONIAN, MID
	2075
4. Well Location	
Unit Letter N: 330 feet from the South line and 1650 feet from the West line Section 08 Township 18S Range 35E NMPM LEA County NM	
11. Elevation (Show whether DR,	
12. Check Appropriate Box to Indicate Nature of Notice, Re	port or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐	REMEDIAL WORK ALTERING CASING 'COMMENCE DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB /
OTHER:	
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.	
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with	
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have	
to be removed.)	
All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-	
retrieved flow lines and pipelines.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well location, except for utility's distribution infrastructure.	
~.	
When all work has been completed, return this form to the appropriate D	strict office to schedule an inspection.
SIGNATURE SIL CL TITLE IV	oduction to reman DATE 12/1/14
TYPE OR PRINT NAME Bob Akin E-MAIL: For State Use Only	rakin@linnenergy, comphone: 575 390 8007
N. J. I. Williams One Office of the Control of the	empliance Officer DATE 1/6/2015
APPROVED BY: TITLE Conditions of Approval (if any):	mphance Aticer DATE 1/6/2015
Conditions of Approval (if any).	\mathcal{M}_{\sim}
	JAN 0 7 2015