Submit One Copy To Appropriate District Office	State of New Mexico		Form C-103
District I	Energy, Minerals and Natural Resources		Revised November 3, 2011
1625 N, French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-025-32425
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE S FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87505		6. State Oil & Gas Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			CAPROCK MALJAMAR UNIT
PROPOSALS.) 1. Type of Well: ⊠Oil Well □ 0	Gas Well Other	UI (A BARACIA)	8. Well Number 165
2. Name of Operator	,	nuddo suud	9. OGRID Number
LINN OPERATING INC		1001 0 0 2015	269324 10. Pool name or Wildcat
3. Address of Operator 600 TRAVIS, SUITE 5100, HOUST	ON TX 77002	JAN 2 6 2015	MALJAMAR;GRAYBURG-SAN ANDRES
	OII, 17177002		IVA ESTE MAÇORET PORCE OTAL TELES
4. Well Location RECEIVED			
Unit Letter M: 66 feet from the South line and 1256 feet from the West line			
Section 17 Township 17S Range 33E NMPM LEA County NM			
	11. Elevation (Show whether	DR, RKB, RT, GR, etc.	
12. Chook Appropriate Poy to		Panart or Other F	Notes
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INT			SEQUENT REPORT OF:
 -	PLUG AND ABANDON		
TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL	COMMENCE DR	_
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB []
OTHER: Location is ready for OCD inspection after P&A			
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
11 Steel marker at reast 1. In diameter and at reast 1. door o ground to verifus been set in concrete. It shows the			
OPERATOR NAMÉ, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment.			
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.) All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
	• • • •		
location, except for utility's distribution infrastructure. A PdA marker below Ground ?			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE	TITLE	Production S	pecialist DATE 1/21/15
			·
TYPE OR PRINT NAME Varren	Souter E-MAI	IL: OISOUTER	linnenergy comphone, 575-369-9113
For State Use Only			
(APPROVED BY: Wall Whitalam TITLE Compliance Officer DATE 1/29/2015			
Conditions of Approval (if any):			