Submit One Copy To Appropriate District	State of New Mexico			Form C-103
Office District I	Energy, Minerals and Natural Resources		Revised November 3, 2011	
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-025-33083
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		r.	STATE STEE
District IV	Santa Fe, NM 87505			6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	ES AND REPORTS O		v. mo .	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA				CAPROCK MALJAMAR UNIT
PROPOSALS.)		HOBBSO		8. Well Number 175
 Type of Well:	ias well Other			9. OGRID Number
LINN OPERATING INC		JAN 26	2015	269324
3. Address of Operator				10. Pool name or Wildcat
600 TRAVIS, SUITE 5100, HOUST	ON, TX 77002	RECEWA	sn	MALJAMAR;GRAYBURG-SAN ANDRES
4. Well Location		napo par		
Unit Letter D: 1302 feet from the North line and 1367 feet from the West line				
Section 19 Township 17S Range 33E NMPM LEA County NM				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
4,105' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INT			SUBS	SEQUENT REPORT OF:
<u> </u>	PLUG AND ABANDON		EDIAL WORK	_
	CHANGE PLANS MULTIPLE COMPL		MENCE DRIL NG/CEMENT	LING OPNS. PAND A
I OLE ON ALTER GASING	WIOLITI LL COIVII L	LI JOAGI	- INCOCCIVILIA I	J J
OTHER:			ocation is re	ady for OCD inspection after P&A
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
elemente de seus de la composition de l				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)				,
All other environmental concerns			5 10 NMAC	All fluids have been removed from non-
retrieved flow lines and pipelines.	i avandoned in accorda	ince with 19.13.3.	J. IU MIVIAC.	All fluids have been removed from hon-
If this is a one-well lease or last re		all electrical serv	ice poles and	lines have been removed from lease and well
location, except for utility's distribution	n infrastructure.			3 kg.
When all work has been completed, ret	turn this form to the an	nronriate District	office to sche	edule an inspection.
		•		. · · · · · · · · · · · · · · · · · · ·
SIGNATURE V				ecialist DATE 1/21/15
TYPE OR PRINT NAME Darren	Seatur	E-MAIL:	ter Olini	venergy com PHONE: 1575-369-9113
For State Use Only	\bigcap	Λ		
APPROVED BY: Wall	Thi-Jaken	TITLE CIM	slian.	Officer DATE 1/29/2015
Conditions of Approval (if any):		11100		DATE -