State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION		
DISTRICT I 1625 N. French Dr. , Hobbs, NM 88240	1220 South	St. Francis Dr. NM 87505	WELL API NO. 30-025-05540	/
DISTRICT II	Sama i e,	14111 07005	5. Indicate Type of Lease	
1301 W. Grand Ave, Artesia, NM 88210			STATE X	FEE
DISTRICT III			6. State Oil & Gas Lease No.	
1000 Rio Brazos Rd, Aztec, NM 87410				~
SUNDRY NO	TICES AND REPORTS ON WE	LLS	7. Lease Name or Unit Agreen	ment Name OOD
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		North Hobbs (G/SA) Unit	RODES	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals.)		Section 36	\$ 2015	
1. Type of Well:	,	, ,	8. Well No. 321	EER OB
Oil Well	Gas Well Other To	emporarily Abandoned		FED
Name of Operator Occidental Permian Ltd.			9. OGRID No. 157984	DECEMED
3. Address of Operator			10. Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX	79323			110003 (0/5/1)
4. Well Location		· ••••	<u> </u>	····
Unit Letter G : 1650	Feet From The North	1650 Fee	t From The East	Line
Section 36	Township 18-S	Range 37-E	E NMPM	Lea County
	11. Elevation (Show whether DF, Ri 3663' GL	KB, RT GR, etc.)		
			Vallatatatata	
Pit or Below-grade Tank Application	or Closure	•		
Pit Type Depth of Ground	d Water Distance from r	earest fresh water well	Distance from nearest su	ırface water
Pit Liner Thickness mil	Below-Grade Tank: Volume	bbls: Construction Ma	terial	
		, , , , , , , , , , , , , , , , , , , 		
17 E-PERMITTING		ture of Notice, Report, or C	Other Data SEQUENT REPORT O	F:
P&A NR	P&A R	REMEDIAL WORK		
P INT TO P&A	COMP	REMEDIAL WORK	ALTERING	CASING
INT TO P&A	COMP	COMMENCE DRILLING OPI	ALTERING	
INT TO P&A	COMP		ALTERING	CASING
INT TO P&A	COMP	COMMENCE DRILLING OPI CASING TEST AND CEMEN	ALTERING NS. PLUG & A	CASING
CSNG RBDI	COMPCHG-Loc	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Casing integri	ALTERING NS PLUG & A IT JOB ty test/TA status request	CASING MBANDONMENT X
INT TO P&A	COMP	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Casing integri etails, and give pertinent dates	ALTERING NS. PLUG & A IT JOB ty test/TA status request , including estimated date of s	CASING MBANDONMENT X
TI CSNG P TA RBDI 13. Describe Proposed or Completed Op	COMP	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Casing integri etails, and give pertinent dates	ALTERING NS. PLUG & A IT JOB ty test/TA status request , including estimated date of s	CASING MBANDONMENT X
TI CSNG P TA RBDI 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103.	COMP	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Casing integri etails, and give pertinent dates wellbore diagram of proposed of	ALTERING NS. PLUG & A IT JOB ty test/TA status request , including estimated date of s	CASING MBANDONMENT X
TI CSNG P TA RBDI 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015	COMP	COMMENCE DRILLING OPI CASING TEST AND CEMEN OTHER: Casing integri etails, and give pertinent dates wellbore diagram of proposed of	ALTERING NS. PLUG & A IT JOB ty test/TA status request , including estimated date of s	CASING MBANDONMENT X
PINT TO P&A TI CSNG POTA 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I	COMP	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sompletion or recompletion.	E CASING ABANDONMENT X Itarting any
Ti CSNG P TA RBDI 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO	COMP	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of the company o	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of secompletion or recompletion.	E CASING ABANDONMENT X Itarting any
Ti CSNG P TA RBDI 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO CIBP @4060'	COMP	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of the company o	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sompletion or recompletion.	E CASING ABANDONMENT X Itarting any
Ti CSNG P TA RBDI 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO	COMP	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of the company o	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of secompletion or recompletion.	E CASING ABANDONMENT X Itarting any
PINT TO P&A Ti CSNG PTA 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO CIBP @4060' Top perf @4156'	erations (Clearly state all pertinent d For Multiple Completions: Attach v	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of This Apparatus Abando	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sompletion or recompletion.	E CASING ABANDONMENT X Itarting any
INT TO P&A Ti CSNG P TA 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO CIBP @4060' Top perf @4156' Thereby certify that the information above is constructed or	erations (Clearly state all pertinent d For Multiple Completions: Attach v 5 min – 575 PSI; 30 min – 575 PS	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of the Abando delege and belief. I further certify the comments of the comments o	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sompletion or recompletion.	E CASING ABANDONMENT X Itarting any
PINT TO P&A Ti CSNG PTA 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO CIBP @4060' Top perf @4156' I hereby certify that the information above is	erations (Clearly state all pertinent d For Multiple Completions: Attach v	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of This Apical Abando ledge and belief. I further certify or an (attached) alternative	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sompletion or recompletion.	E CASING ABANDONMENT X Itarting any
INT TO P&A Ti CSNG P TA 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO CIBP @4060' Top perf @4156' Thereby certify that the information above is constructed or	erations (Clearly state all pertinent d For Multiple Completions: Attach v 5 min – 575 PSI; 30 min – 575 PS true and complete to the best of my know , a general permit	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of the company of the case of the cas	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sempletion or recompletion. Droval of Temporal that any pit or below-grade tank in e OCD-approved	ABANDONMENT X Starting any A29/2016 has been/will be
PINT TO P&A Ti CSNG PTA 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO CIBP @4060' Top perf @4156' Thereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE	erations (Clearly state all pertinent d For Multiple Completions: Attach v 5 min – 575 PSI; 30 min – 575 PS true and complete to the best of my know , a general permit	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of the company of the control o	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sompletion or recompletion. Prova of Vertical Completion of the com	ABANDONMENT X Starting any ABANDONMENT X Starting any ABANDONMENT ABANDONMENT X Starting any
INT TO P&A Ti CSNG P TA RBDI 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO CIBP @4060' Top perf @4156' I hereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. J	erations (Clearly state all pertinent d For Multiple Completions: Attach v 5 min – 575 PSI; 30 min – 575 PS true and complete to the best of my know , a general permit	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of the company of the case of the cas	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sempletion or recompletion. Droval of Temporal that any pit or below-grade tank in e OCD-approved	ABANDONMENT X Starting any A29/2016 has been/will be
PINT TO P&A Ti CSNG PTA 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO CIBP @4060' Top perf @4156' Thereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE	erations (Clearly state all pertinent d For Multiple Completions: Attach v 5 min – 575 PSI; 30 min – 575 PS true and complete to the best of my know , a general permit	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of the company of the control o	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sompletion or recompletion. Prova of Vertical Completion of the com	ABANDONMENT X Starting any ABANDONMENT X Starting any ABANDONMENT ABANDONMENT X Starting any
INT TO P&A Ti CSNG P TA RBDI 13. Describe Proposed or Completed Opproposed work) SEE RULE 1103. Date of test: 01/29/2015 Pressure readings: Initial – 565 PSI; I Length of test: 30 minutes Witnessed: NO CIBP @4060' Top perf @4156' I hereby certify that the information above is constructed or closed according to NMOCD guidelines SIGNATURE TYPE OR PRINT NAME Mendy A. J	erations (Clearly state all pertinent d For Multiple Completions: Attach v 5 min – 575 PSI; 30 min – 575 PS true and complete to the best of my know , a general permit	COMMENCE DRILLING OPICASING TEST AND CEMENOTHER: Casing integrietails, and give pertinent dates wellbore diagram of proposed of the company of the control o	ALTERING NS. PLUG & A IT JOB ty test/TA status request including estimated date of sompletion or recompletion. Prova of Vertical Completion of the com	ABANDONMENT X Starting any ABANDONMENT X Starting any ABANDONMENT ABANDONMENT X Starting any

FEB 0 9 2015.

M

