

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name Tax/AD		API Number 30-025-35914 -
Property Name Bowers A Fed		Well No. 44 -

Surface Location									
Cl.	Lot	Section	Township	Range	Feet from	N/S Line	Feet from	E/W Line	County
	m	29	18	38	719	S	800	W	LRA

Well Status										
YES	TA'D WELL	NO	YES	SHUT-IN	NO	INJ	INJECTOR	SWD	PRODUCER	DATE
								OIL		2/10/15

OBSERVED DATA

	Surface	Interval 1	Interval 2	Interval 3	Interval 4	Interval 5
Pressure	0	N/A	N/A		70	70
Flow Characteristics						
Flow	Y	N	Y	N	Y	N
Steady flow	Y	N	Y	N	Y	N
Burges	Y	N	Y	N	Y	N
Down to nothing	Y	N	Y	N	Y	N
Gas or Oil	Y	N	Y	N	Y	N
Water	Y	N	Y	N	Y	N

Remarks - Please state on each string (A, B, C, D, E) pertinent information regarding over- or under- or continuous down or up if applies.

Sub Pump

BS 2/12/2015

Signature: Paul Abenado	OIL CONSERVATION DIVISION
Printed name:	Entered into RBDMS
Title:	Re-test
E-mail Address:	
Date: 2/10/15	Phone:
Witness: John Bowers	

FEB 17 2015

h