UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMO	OCD	FORM APPROVI OME 10. 1004-0: Expires: July 31, 20	134
		Serial No. MOSO258	

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					1410114101000230			
					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.			
1. Type of Well ☐ Gas Well ☐ Other ☐ Other					8. Well Name and No. GARNET FEDERAL 6			
2. Name of Operator Contact: SUSAN B MAUNDER CONOCOPHILLIPS COMPANY E-Mail: Susan.B.Maunder@conocophillips.com					9. API Well No. 30-025-41925			
3a. Address 600 N. DAIRY ASHFORD RD HOUSTON, TX 77079-1175		3b. Phone No. (include area (1985))			10. Field and Pool, or Exploratory MALJAMAR; YESO WEST			
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			FFR	1 3 2015	11. County or Parish, and State			
Sec 15 T17S R32E Mer NMP SESE 685FSL 270FEL			(C)(C)	apriler	LEA COUNTY COUNTY, NM			
				CEIVED				
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE I	NATURE OF	NOTICE, RE	PORT, OR OTHER	₹ DATA		
TYPE OF SUBMISSION								
□ Notice of Intent	☐ Acidize ☐ □		en	□ Producti	on (Start/Resume)	■ Water Shut-Off	ĩ	
_	☐ Alter Casing	☐ Fracti	ire Treat	☐ Reclama	tion	■ Well Integrity		
Subsequent Report	Casing Repair	□ New	w Construction					
☐ Final Abandonment Notice	☐ Change Plans	Plug a	Plug and Abandon		rily Abandon	Well Spud		
	Convert to Injection		g Back		Disposal			
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Abdetermined that the site is ready for fit ConocoPhillips Company resp depth. 07/23/14 ? Move rig to Garnet 07/23/14 - Drill to 955? TD. Ru	rk will be performed or provide operations. If the operation repandonment Notices shall be filinal inspection.) pectfully submits this report. Federal 6. Spud well with	the Bond No. on a sults in a multiple ed only after all re rt of spud, casi	file with BLM/BIA completion or rec quirements, including ng setting, and	A. Required sub completion in a n ding reclamation d reaching tot	sequent reports shall be to interval, a Form 3160, have been completed, a	filed within 30 days 0-4 shall be filed once		
csg STC; land csg; shoe at 94 R/U cmt equip. Pumped lead s slurry 72 bbls (310 sx) 14.8 pp Floats held. Circulated 68 bbls 07/24/14 - TIH; test csg 1500 965?. Test good. EMW = 12.8 07/27/14? TD?d well at 7095/07/28/14? Run 170 jts of 5-1/2	.1'. slurry 90 bbls (300sxs), 1: slurry 90 bbls (300sxs), 1: og + adds, yield 1.33. Disp (226 sx) cmt to surface. psi; drlg cmt, shoe track a Drill prod hole w/ 7-7/8??. BHL=964' FSL and 3652" 17#, L-80, LTC csg. Inc.	3.6 ppg + adds blaced w/ 58 bl and 10' formatio bit. b'FEL	, yield 1.69; fo ols FW. Bumpe on, circ, perfor	ollowed by tail ed plug w/ 859 m FIT at		N. P.		
14. I hereby certify that the foregoing is	Electronic Submission #2	PHILLIPS COM	PANY, sent to	the Hobbs				
Name(Printed/Typed) SUSAN B MAUNDER		Title SENIOR REGULA		R REGULAT	ORY SPECIALIST			
Signature (Electronic S	Submission)		Date 08/08/2	2014 ACC	FPTFD FOF	RECORD		
	THIS SPACE FO	R FEDERAL		1 2 2 2 2 3	F			
					P20 1A	AAGE		
_Approved By			Title		FEB 12 2	2015 Date	-	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office	DI	DEALL OF LAND M	3		
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a	crime for any pers	on knowingly and	d willfully to ma	ce coany department or I	agency of the United		

Additional data for EC transaction #256427 that would not fit on the form

32. Additional remarks, continued

R/U cmt equipment; test lines. Cmt w/40 bbl FW spacer, then 550 sxs (222 bbls) of 50:50 Class "C" poz lead cement + additives mixed @ 11.8 ppg w/ 2.27 yield & 12.72 mix H2O. Tail slurry-860 sxs (211 bbls) TXI cement mixed @ 13.2 ppg w/ 1.38 yield & 6.84 mix H2O. Displace w/164 bbls FW w/biocide. Circ?d 63 bbls (156 sxs) cmt to surface. Bump plug @ 1950-2500psi; floats held. RD. 7/28/14 ? Pressure test tubing head 5000 psi. Test good. Bottom Hole Location=