

Form 3160-5 (August 2007)				

■ Subsequent Report

☐ Final Abandonment Notice

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-013:
Expires: July 31, 201

■ Well Integrity

□ Other

	SUN	IDRY	NOTIC	ES AN	D REPO	ORTS (ON WE	LLS	
Do	not u	use thi	s form	for prop	osals to	o drill o	r to re-	enter	an

Lease Serial No. NMLC062486

SUNDRY N	DINCES AND REPORTS ON WELLS
Do not use this	form for proposals to drill or to re-enter an
	Use form 3160-3 (APD) for such proposals

abandoned we	o. If findian, Afforce of Thoe Name			
SUBMIT IN TR	PLICATE - Other instruc	tions on reverse side.	7. If Unit or CA/Agreement, Name and/or No. 8910063990	
1. Type of Well			Well Name and No. DRICKEY QUEEN SAND UNIT 824	
☑ Oil Well ☐ Gas Well ☐ Ot	her		DRICKET QUEEN SAND UNIT 824	
Name of Operator LEGACY RESERVES OPER.		LAURA PINA cylp.com	9. API Well No. 30-005-00989-00-S1	
3a. Address		3b. Phone No. (include area code)	10. Field and Pool, or Exploratory	
PO BOX 10848 MIDLAND, TX 79702		Ph: 432-689-5200 Ext: 5273	CAPROCK-QUEEN	
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)	HORPS	11. County or Parish, and State	
Sec 4 T14S R31E NENW 665 33.137603 N Lat, 103.827823		MAY 18 20	CHAVES COUNTY, NM	
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE NATURE CENT	DICE, REPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent		☐ Deepen	☐ Production (Start/Resume) ☐ Water Shut-Off	

□ Convert to Injection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

☐ Plug Back

☐ Fracture Treat

■ New Construction

□ Plug and Abandon

□ Reclamation

□ Recomplete

■ Water Disposal

▼ Temporarily Abandon

Legacy Reserves Operating LP respectfully requests TA for two years Subject well has future service as a producing well when the planned CO2 injection for the DQSU is expanded to this area of the filed/lease.

1. POOH LD rods & pump. Stand back tubing for workstring. Make a bit and scraper run to 2770' and POOH.

2. RIH and set a CIBP at 2725'. Spot 10 sx cement on CIBP, WOC a minimum of 4 hrs, tag TOC, pressure test casing to 500 psi, and circulate hole w/inhibited freshwater. POOH leaving 1 joint w/minimum 1500 psi WP valve at surface.

3. Chart casing to 500 psi for 30 minutes and submit to BLM.

4. Flush flow line w/freshwater from well back to battery and clean location.

☐ Alter Casing

□ Casing Repair

□ Change Plans

Current and proposed wellbore sketches are attached.

14. I hereby certify that th	ne foregoing is true and correct. Electronic Submission #299909 verifie For LEGACY RESERVES OPE Committed to AFMSS for processing by DA	RATIN	S, sent to the Roswell	
Name (Printed/Typed)	LAURA PINA	Title	AUTHORIZED REPRESENTATIVE	
Signature	(Electronic Submission)	Date	04/29/2015	
	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE	٠.
Approved By DAVID R		TitleF	ETROLEUM ENGINEER	Date 05/11/2015
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Roswell	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or représentations as to any matter within its jurisdiction.

NUBJOCA 5/18/201

SEE ATTACHED FORM REVISEAPI **CONDITIONS OF APPROVAL**

LEGACY RESERVES LP DATE: 13-Apr-15 FIELD: Caprock MWM BY: DQSU (formerly Trigg Federal #24) LEASE/UNIT: WELL: 824 **COUNTY:** Chaves STATE: **New Mexico** Location: 665' FNL & 2310' FWL, Sec 4C, T14S, R31EC KB = 4165'SPUD: 06/17/56 COMP: 07/56 GL = 4129'**CURRENT STATUS: Producer** API = 30-005-00989Original Well Name: Federal Trigg #24-4 8-5/8" 24# J-55 @ 105' w/50 sx, circ'd T-Anhy @ 1100'-est T-Salt @ 1220'-est B-Salt @ 1860'-est T-Yates @ 2000'-log T-Queen @ 2775' **EXISTING** 2 7/8" 6.5# J-55 production tubing @ 2735' 7 7/8" TOC @ 2240' (CBL, 10/07) 5-1/2" 14# J-55 @ 2770' w/100 sx Top of Queen @ 2775': Queen Open Hole: 2775' - 2788' (06-56) **Queen Open Hole: 2775' - 2830' (10-07)** PBTD - 2830' TD - 2830'

LEGACY RESERVES LP DATE: 13-Apr-15 FIELD: Caprock BY: MWM **DQSU** (formerly Trigg Federal #24) LEASE/UNIT: WELL: 824 COUNTY: Chaves STATE: **New Mexico** Location: 665' FNL & 2310' FWL, Sec 4C, T14S, R31EC KB = 4165'SPUD: 06/17/56 COMP: 07/56 GL = 4129' **CURRENT STATUS: Producer** API = 30-005-00989Original Well Name: Federal Trigg #24-4 8-5/8" 24# J-55 @ 105' w/50 sx, circ'd T-Anhy @ 1100'-est T-Salt @ 1220'-est B-Salt @ 1860'-est T-Yates @ 2000'-log T-Queen @ 2775' 7 7/8" TOC @ 2240' (CBL, 10/07) CIBP at 2725' cap w/10 sx 5-1/2" 14# J-55 @ 2770' w/100 sx Top of Queen @ 2775': Queen Open Hole: 2775' - 2788' (06-56) Queen Open Hole: 2775' - 2830' (10-07) PBTD - 2830' TD - 2830'

BUREAU OF LAND MANAGEMENT

Roswell Field Office 2909 West Second Street Roswell, New Mexico 88201 575-627-0272

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporary abandoned well is defined as a completion that is not capable of production in paying quantities but may have value as a service well. Pursuant to 43 CFR 3162.3-4(c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
- A. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
- B. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.
- C. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
- D. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
- E. Contact the BLM Roswell Field Office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Chaves and Roosevelt County, during office hours or after office hours call (575) 627-0205. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status up to 12 months.

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval.
- 2. Attaches a clear copy of the original pressure test chart.
- 3. Provided justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.
- 4. Describes the temporary abandonment procedure.

The TA status could be extended without another casing integrity test provided there was no leak-off during the test and the test was witnesses by a BLM representative.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Ref: IM: NM-95-022 (12/16/1994)