Submit One Copy To Appropriate District		•	<b>F</b> C 102
Office	State of New MEXICO		Form C-103 Revised November 3, 2011
District I 1625 N. French Dr., Hobbs, NM 88240	N. French Dr., Hobbs, NM 88240		WELL API NO.
District II 811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		30-025-34210 5. Indicate Type of Lease	
District III 1220 South St. Francis Dr.		STATE $\boxtimes$ FEE	
District IV Santa Fe, NM 8/505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			VA-764
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG ACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Pluma ASD State Com
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other			8. Well Number 001
2. Name of Operator			9. OGRID Number
EnerVest Operating, LLC /	RE	E C	143199
3. Address of Operator	FIL	15	10. Pool name or Wildcat
1001 Fannin, Ste 800, Houston, TX 770	)02 <b>%</b>		Tulk; Wolfcamp
4. Well Location			
Unit Letter L: <u>1650</u> feet from the <u>South</u> line and <u>660</u> feet from the <u>West</u> line			
Section 10         Township 15S         Range 32E         NMPM         Lea County           11. Elevation (Show whether DR, RKB, RT, GR, etc.)         11. Elevation (Show whether DR, RKB, RT, GR, etc.)         11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
4296' GR			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
		BSEQUENT REPORT OF:	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR			
		CASING/CEMEN	
OTHER:       Image: Constraint of the constr			
<ul> <li>Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.</li> </ul>			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-			
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution		F F	· · · · · · · · · · · · · · · · · · ·
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE Shelly Dec	Achen TITLE	E Agent	DATE 06-18-2015
TYPE OR PRINT NAME Shelly Doescher E -MAIL: sdoescher@enervest.net PHONE: 505-320-5682			
For State Use Only			
APPROVED BY: Malutidue TITLE Compliance Africar DATE 6/25/15			
Conditions of Approval (if any):			

JUN 2 6 2015

Ŋ