

JUL 10 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name Chevron USA Inc	APT Number 30-025-31837
Property Name Vacuum Gloriaeta West Unit	Well No. 11

2. Surface Location

UL - Loc B	Section 25	Township 17S	Range 34E	Feet from 246	N/S Line N	Feet From 1554	E/W Line E	County LEA
----------------------	----------------------	------------------------	---------------------	-------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

TA'D WELL. <input checked="" type="checkbox"/>	NO <input checked="" type="checkbox"/>	YES <input checked="" type="checkbox"/>	SHUT-IN <input checked="" type="checkbox"/>	NO <input checked="" type="checkbox"/>	INJ <input checked="" type="checkbox"/>	SWD <input type="checkbox"/>	OIL <input type="checkbox"/>	PRODUCER <input type="checkbox"/>	GAS <input type="checkbox"/>	DATE 5/7/15
---	---	--	--	---	--	---------------------------------	---------------------------------	--------------------------------------	---------------------------------	-----------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	0	N/A	N/A	0	1200
Flow Characteristics					
Pull	Y/N	Y/N	Y/N	Y/N	CO2 <input type="checkbox"/>
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR <input type="checkbox"/>
Surges	Y/N	Y/N	Y/N	Y/N	GAS <input type="checkbox"/>
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

BS 7/14/2015

Signature: Tanner Chevron	OIL CONSERVATION DIVISION
Printed name: Tanner Patton	Entered into RBDMS
Title: FSA	Re-test
E-mail Address: Tpatt@chevron.com	
Date: 5/7/15	Phone:
Witness: [Signature]	

JUL 16 2015

INSTRUCTIONS ON BACK OF THIS FORM

h