

Submit One Copy To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88240

District II

1301 W. Grand Ave., Artesia, NM 88210

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
January 20, 2011

WELL API NO.  
30-025-37436

5. Indicate Type of Lease  
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.  
V-6593

7. Lease Name or Unit Agreement Name

Mustang State

8. Well Number 2

9. OGRID Number  
229137

10. Pool name or Wildcat  
Vacuum; GBRG-SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: ☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

COG Operating LLC

3. Address of Operator One Concho Center  
600 W Illinois Ave, Midland, TX 79701

4. Well Location

Unit Letter O : 977 feet from the South line and 1681 feet from the East line  
Section 18 Township 17S Range 36E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
3905' GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

☒ Location is ready for OCD inspection after P&A

- ☒ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  
☒ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  
☒ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the

**OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.**

- ☒ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.  
☒ Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.  
☒ If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.  
☒ All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)  
☒ All other environmental concerns have been addressed as per OCD rules.  
☒ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.  
☒ If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service company equipment, has been removed from lease and well location.

When all work has been completed, return this form to the appropriate District office to schedule an inspection.

SIGNATURE

TITLE Lead Regulatory Analyst

DATE 04/23/15

TYPE OR PRINT NAME Kanicia Castillo

E-MAIL: kcastillo@concho.com

PHONE: 432/685-4332

For State Use Only

APPROVED BY: Mah Whitman

TITLE Compliance Officer

DATE 8/3/2015

Conditions of Approval (if any):

AUG 03 2015



July 29, 2015

New Mexico Oil Conservation Division  
Attn: Mark Whitaker  
1625 N French Drive  
Hobbs, NM 88240

HOBBS OCD  
JUL 31 2015  
RECEIVED

Re: Letter of Violation - Inspection

Mustang State #2  
Lea County, NM  
API # 30-025-37436

Dear Mr. Whitaker,

COG has completed the work requested on the violation letter.

- Steel plate has been replaced.
- 4 poles have been removed.
- Gas meter rack has been removed.
- Caliche has been removed.

I have attached the following documents:

- ☐ Bill of Sale – Rancher requested the tanks to be left on property.

*Day Angel mw 8/3/15*

Location is ready for inspection.

Please contact me at 432-686-3087 or e-mail at [cjackson@concho.com](mailto:cjackson@concho.com) if you need additional information.

Thank you,

*Chasity Jackson*

Chasity Jackson  
COG Operating LLC  
Regulatory Analyst