

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division Hobbs District Office

AUG 13 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name OCCIDENTAL PERMIAN, LTD	API Number 30-025-05468
Property Name NORTH HOBBS (G/SA) UNIT	Well No. 412

Surface Location

UL - Lot A	Section 23	Township 18-S	Range 37-E	Feet from 990	N/S Line NORTH	Feet From 760	E/W Line EAST	County LEA
---------------	---------------	------------------	---------------	------------------	-------------------	------------------	------------------	---------------

Well Status

TA'D WELL <input checked="" type="radio"/> YES <input type="radio"/> NO	SHUT-IN <input checked="" type="radio"/> YES <input type="radio"/> NO	INJ	INJECTOR SWD	PRODUCER <input checked="" type="radio"/> OIL <input type="radio"/> GAS	DATE 6-26-15
--	--	-----	-----------------	--	-----------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	Ø	Ø	N/A	Ø NA	N/A
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 ___
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR ___
Surges	Y/N	Y/N	Y/N	Y/N	GAS ___
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if
					applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Surface Puff some water then stopped

ml. e 6-26-15 499-4454

B8 8/29/2015

Signature: <i>Mendy Johnson</i>	OIL CONSERVATION DIVISION
Printed name: MENDY JOHNSON	Entered into RBDMS
Title: ADMINISTRATIVE ASSOCIATE	Re-test
E-mail Address: mendy_johnson@oxy.com	
Date: AUG 11 2015	Phone: 806-592-6280
Witness:	

INSTRUCTIONS ON BACK OF THIS FORM

SEP 01 2015