


State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

David Martin
Cabinet Secretary

Brett F. Woods, Ph.D.
Deputy Cabinet Secretary

David Catanach, Director
Oil Conservation Division



Response Required - Deadline Enclosed

Field Inspection Program
"Preserving the Integrity of Our Environment"

01-Sep-15

CIMAREX ENERGY CO. OF COLORADO
202 S. CHEYENNE AVE, STE 1000
TULSA OK 74103

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION


COOPER SR No.003				J-23-24S-36E	30-025-25233-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/31/2015	Routine/Periodic	Mark Whitaker	Yes	No	10/30/2015	iMAW1524336792
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		No well sign (Rule 19.15.16.8). NEED TO INSTALL WELL SIGN.				

STATE LG 25 No.001				H-25-16S-33E	30-025-27906-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
08/31/2015	Routine/Periodic	Mark Whitaker	Yes	No	10/30/2015	iMAW1524351846
Violations						
Absent Well Identification Signs (Rule 103)						
Comments on Inspection:		Operator of record no legible on well sign (Rule 19.15.16.8). NEED TO CORRECT SIGN.				

SEP 01 2015

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,



Compliance Officer

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER

FIRST-CLASS MAIL

\$000.48⁵

09/01/2015 ZIP 88240
012E14642224

US POSTAGE

CIMAREX ENERGY CO. OF COLORADO
202 S. CHEYENNE AVE.
SUITE 1000
TULSA, OK 74103