## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

**David Martin** 

Cabinet Secretary

Brett F. Woods, Ph.D. Deputy Cabinet Secretary

David Catanach, Director Oil Conservation Division



## \*Response Required - Deadline Enclosed\*

Field Inspection Program
"Preserving the Integrity of Our Environment"

04-Sep-15

LEGACY RESERVES OPERATING, LP

P. O. BOX 10848 MIDLAND TX 79702

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

	INSPECTION	V DETAIL	SECTION		
MATTIX PENROSE SAND	UNIT No.102 Inspector	Violation?	K-21-22S-37E *Significant Non-Compliance?	30-025-10384-00-0 Corrective Action Due By:	Inspection No.
Routine/Periodic	Gilbert Cordero	Yes	No	12/8/2015	iGC1524737241
on Inspection: No Well Sign	(Rule 19.15.16.8). Ne	ed to install	well sign. First notice		
MATTIX PENROSE SAND	UNIT No.103	Violation?	J-21-22S-37E *Significant Non-Compliance?	30-025-10388-00-0 Corrective Action Due By:	Inspection No.
Routine/Periodic	Gilbert Cordero	Yes	No	12/8/2015	iGC1524737792
on Inspection: No Well Sign	(Rule 19.15.16.8). Ne	ed to install	well sign. First notice		
MATTIX PENROSE SANI	UNIT No.084	Violation?	E-21-22S-37E *Significant Non-Compliance?	30-025-23770-00-0 Corrective Action Due By:	100 Inspection No.
I VDC Inspection					
	Type Inspection Routine/Periodic on Inspection: No Well Sign MATTIX PENROSE SAND Type Inspection Routine/Periodic on Inspection: No Well Sign	Type Inspection Inspector Routine/Periodic Gilbert Cordero on Inspection: No Well Sign (Rule 19.15.16.8). New MATTIX PENROSE SAND UNIT No.103 Type Inspection Inspector Routine/Periodic Gilbert Cordero	Type Inspection Inspector Violation? Routine/Periodic Gilbert Cordero Yes on Inspection: No Well Sign (Rule 19.15.16.8). Need to install  MATTIX PENROSE SAND UNIT No.103  Type Inspection Inspector Violation? Routine/Periodic Gilbert Cordero Yes on Inspection: No Well Sign (Rule 19.15.16.8). Need to install	Type Inspection	MATTIX PENROSE SAND UNIT No.102  Type Inspection Inspector Routine/Periodic Inspector No Well Sign (Rule 19.15.16.8). Need to install well sign. First notice  MATTIX PENROSE SAND UNIT No.103 Type Inspection Inspector Type Inspection Routine/Periodic Gilbert Cordero Type Inspection Inspector Type Inspection

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Complance Oft

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER FIRST-CI

IRST-CLASS MAI

\$000.48<sup>5</sup>

09/04/2015 ZIP 88240 012E14642224

LEGACY RESERVES OPERATING, LP P. O. BOX 10848 MIDLAND TX. 79702