<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 811 S. First St., Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-129

SEP 1 1 2015 Revised August 1, 2011

Submit one copy to appropriate District Office

RECEIVED No.

NFO Permit

HOBBS OCD

(For Division Use Only)

APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12

(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)

A.	ApplicantMurchison Oil & Gas, Inc,	
	whose address is7250 Dallas Parkway, Ste. 1400, Plano, TX 75024,	
	hereby requests an exception to Rule 19.15.18.12 for days or until,	
	, Yr, for the following described tank battery (or LACT):	
	Name of Lease <u>Jackson Unit 15H (30-025-41086)</u> Name of Pool <u>Triple X</u> ; <u>Bone Spring</u> , <u>West</u>	
	Location of Battery: Unit Letter <u>C</u> S	ection 15 Township 24S Range 33E
	Number of wells producing into battery	<u>2</u>
В.	Based upon oil production of75	barrels per day, the estimated * volume
	of gas to be flared isMC	F; Valueper day.
C.	Name and location of nearest gas gathering facility:	
	Frac Cat Compressor Station, Lea County, N	<u>M</u>
D.	DistanceEst	imated cost of connection
E.	This exception is requested for the following reasons: <u>Intermittent curtailment by Agave due to compressor maintenance</u> . Well shut in at this time may damage formation and reduce future production.	
	compressor maintenance. Wen shut in at this	s time may damage formation and reduce future production.
I hereby certify that the rules and regulations of the Oil Conservation		OIL CONSERVATION DIVISION
Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.		Approved Until $12/9/2015$
Signature		Approved Until 12/9/2015 By Mafey S Frown
Printed Name & Title Gary Cooper, Vice President Operations		Title District Supervisor
Email Address rcooper@jdmii.com		Date 9/14/2015
Date 9/9/15 Telephone No. 972-931-0700		/ /
* Gas-Oil ratio test may be required to verify estimated gas volume.		