

AUG 28 2015

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

RECEIVED

BRADENHEAD TEST REPORT

Operator Name
ENERGYQUEST II, LLC

API Number
3002503563

Property Name
MERRELL

Well No.
1

7. Surface Location

UL - Lot H	Section 10	Township 9S	Range 36E		Feet from 1980	N/S Line N	Feet From 330	E/W Line E	County LEA
----------------------	----------------------	-----------------------	---------------------	--	--------------------------	----------------------	-------------------------	----------------------	----------------------

Well Status

TA'D WELL YES	<input checked="" type="radio"/> NO	<input checked="" type="radio"/> YES	SHUT-IN NO	INJ	INJECTOR <input checked="" type="radio"/> SWD	PRODUCER OIL	GAS	DATE 08/26/2015
------------------	-------------------------------------	--------------------------------------	---------------	-----	--	-----------------	-----	---------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csgng	(E)Tubing
Pressure	0	0	0	0	0
<u>Flow Characteristics</u>					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR _X_
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if - applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: <i>Debra Moore</i>	BS 9/15/2015	
Printed name: DEBRA MOORE	OIL CONSERVATION DIVISION	
Title: PRODUCTION ANALYST	Entered into RBDMS	
E-mail Address: debra.moore@energyquest.us	Re-test	
Date: 08/27/2015	Phone: 281-875-6200	
Witness:		

SEP 16 2015

[Signature]