Submit 1 Copy To Appropriate District Office District I - (575) 393-6161 1625 N. French Dr., Hobbs. NM 88240 District II - (575) 748-1283 811 S. First St., Artesia, NM 88210 District III - (505) 334-6178 1000 Rio Brazos Rd., Aziec, NM 87410 District IIV - (505) 476-3460 RECEIVED Sundry Notices And Reports on Wells (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other 2. Name of Operator State of New Mexico formerly Canyon E&P Company 3. Address of Operator 1625 N. French Drive Hobbs NM 88240	Form C-103 Revised August 1, 2011 WELL API NO. 30-025-28258 5. Indicate Type of Lease STATE FEE X 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name Jameson 8. Well Number 002 9. OGRID Number 10. Pool name or Wildcat Jalmat
4. Well Location Unit Letter_F:1650feet from theNorthline and2310feet from theWestline Section 15	
I hereby certify that the information above is true and complete to the best of my knowled SIGNATURE	
Conditions of Approval (if any):	DATE 10, 1, 2013

Plugging Report Jameson #2

9/22/2015 Moved in rigged up. Unseated pump and laid down 50-- 7/8" rods and 86-- $\frac{3}{4}$ " rods. Nippled down wellhead and dug out cellar. Changed out bad connections on surface head. Installed BOP.

9/23/2015 POOH with tubing. 109 jts of 2 3/8". RIH with gauge rig on wireline and sat down at 3448'. RIH and set 4 ½" CIBP at 3400' as per OCD. Circulated MLF. Good circulation but could not test casing because 4 ½" casing is leaking above the surface head. Called vacuum truck to catch fluid. Spotted 25 sx Class C cement on top of CIBP. POOH to 3014' and spotted 25 sx class c cement. POOH and laid down setting tool. Shut down for thunderstorm. Will remove BOP and inspect wellhead leak in the morning.

9/24/2015 Removed BOP and 4 ½" wellhead. Wellhead had broken almost completely off while tripping out of the hole yesterday. Set packer inside 4 ½" casing below where the wellhead broke off and test the casing to 750#. Held good. Perforated at 1473' and squeezed with 30 sx cement with CaCl. WOC and tagged cement at 1321'. Perforated at 300'. Set packer with 1 joint of tubing and pumped cement down 4 ½" casing to perfs at 300' and up annulus to surface. Used 90 sx.

9/25/2015 V Rigged down. Cut off wellhead and installed marker. Cut off anchors.