

Exhibit 2

api 30-025-21800



		DATE	10/19/2015
COMPANY NAME	06 SWD LLC	COMPANY REP.	Daniel Olivas
BASE	State AK SWD	WELL #	1
TUBING SIZE	2 7/8	CSG SIZE	5-1/2 17#
		JOB DESCRIPTION	

10/19/2015

Drove to location rig pulling unit up, nipple down flange, nipple up bop unset packer rig up scanner log w/ 292 joints lay down 35 bad joints, rig down scanner log close well shut down

10/20/2015

shut down for packer repair

10/21/2015

Drove to location tally 40 new joints ran packer w/ 40 new joints rig up tubing testers test 260 joints @ 5000 psi found 1 bad an lay down 1 joint rig down tubing testers set packer @ 9461' load casing w/ 136 bbls pressure up to 500 psi wand down to 300 psi an 10:mts un seat packer lay down 1 joint set packer @ 9432' load w/ 120 bbls presure up to 500 psi wand down 300 psi on 8: mts close well shut down.

10/22/2015

Drove to location unset packer lay down 1 joint set packer @ 9402' load casing w/ 120 bbls pressure up to 500 psi wand down to 300
lay down 1 joint set packer @ 9370' load casing w/ 120 bbls pressure up to 500 psi wand down 300 psi on 15 mts lay down 6 joints set packer @ 9129' pump 150 bbls down casing cant load un set packer pooh w/ 289 joints close well shut down.

10/23/2015

Drove to location ran new packer 289 joints set packer @ 9129' load casing w/ 126 bbls pressure up to 500 psi left pressure for 15: test ok, got off on an off tool circulate well w/ 180 bbls Packer fluid lash into the on an off tool nipple down bop flange well pressure test casing up to 500 psi 15: mts ok

NOV 05 2015

B8 11/5/15