HOBBS OCD

NOV 0 2 2015

RECEIVED

Submit One Copy To Appropriate District Office	State of New Mexico		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		Revised November 3, 2011 WELL API NO.
<u>District II</u> 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-025-26186 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr. Santa Fe, NM 87505		STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Gas Lease No. L2662
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			7. Lease Name or Unit Agreement Name NEW MEXICO 28 STATE
PROPOSALS.) 1. Type of Well: □Oil Well ☑	Gas Well Other	\checkmark	8. Well Number 001
2. Name of Operator VERNON E. FAULCONER, INC.		1	9. OGRID Number 148394
 Address of Operator 1001 ESE LOOP 323, SUITE 160 	P.O. BOX 7995, TYLER, 1	X 75711	 Pool name or Wildcat 85210 SHOE BAR; ATOKA
4. Well Location			1
	om the SOUTH line and 1980		ne d
Section 28 Township	16S Range 35E NMPM 11. Elevation (Show whether	County LEA	-)
民族意思。而且非常是	4011' RKB		
12. Check Appropriate Box to	Indicate Nature of Notic	e, Report or Other I	Data
NOTICE OF IN			BSEQUENT REPORT OF:
	PLUG AND ABANDON	REMEDIAL WO	= /
TEMPORARILY ABANDON	CHANGE PLANS	CASING/CEMEN	
	_		_
OTHER: All pits have been remediated in	compliance with OCD rules :	Location is	ready for OCD inspection after P&A
Rat hole and cellar have been fi	lled and leveled. Cathodic pro	tection holes have been	n properly abandoned.
A steel marker at least 4" in dia	meter and at least 4' above gro	und level has been set	in concrete. It shows the
OPERATOR NAME, LEA	ASE NAME, WELL NUMBI	ER, API NUMBER, O	UARTER/QUARTER LOCATION OR
UNIT LETTER, SECTIO	N, TOWNSHIP, AND RANG	GE. All INFORMATI	ION HAS BEEN WELDED OR
PERMANENTLY STAM	PED ON THE MARKER'S	SURFACE.	
The location has been leveled as	s nearly as possible to original	ground contour and ha	s been cleared of all junk, trash, flow lines and
other production equipment.	1. 1. 1		
Anchors, dead men, tie downs a			s) have been remediated in compliance with
			oduction equipment and junk have been removed
from lease and well location.	Is have been removed. Dertek	In here a here here a	d (Deved are its second about a second
to be removed.)	is have been removed. Fortab	the bases have been rem	noved. (Poured onsite concrete bases do not have
All other environmental concern			
	en abandoned in accordance v	vith 19.15.35.10 NMA	C. All fluids have been removed from non-
retrieved flow lines and pipelines.	remaining well on lease: all e	lectrical service poles a	nd lines have been removed from lease and well
location, except for utility's distribut			
When all work has been completed,	return this form to the appropr	iate District office to so	chedule an inspection.
and the former	he l.	E BROBHOTION .	NALYST DATE: 11/2/15
SIGNATURE (anen (halleTITL	E: PRODUCTION A	ANALYSI DATE: //////
TYPE OR PRINT NAME: KAREN For State Use Only	CHARLES E-MAIL: 1	charles@vefinc.com_	PHONE: 903-581-4382
APPROVED BY:	Down TITL	E Compliance D	Hice DATE 1/19/15
1704		V mape	NOV 2 3 2015
			NU & G COIG