District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division EC 0 3 2015 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-129 Revised August 1, 2011

Submit one copy to appropriate District Office

NFO Permit No.

(For Division Use Only)

APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12

(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)

| A. | Applicant Murchison Oil & Gas, Inc. | | |
|--|---|---|--|
| | whose address is 7250 Dallas Parkway, Ste. 1400, Plano, TX 75024, | | |
| | hereby requests an exception to Rule 19.15.18.12 for 90 days or until March 9, | | |
| | , Yr2016, for the following described tank battery (or LACT): | | |
| | Name of Lease Bettis 20 State Com 3H (30-025-41437) Name of Pool Triple X; Bone Spring, West | | |
| | Location of Battery: Unit Letter O Section 20 Township 24S Range 33E | | |
| | Number of wells producing into battery1 | | |
| B. | Based upon oil production of125_ | barrels per day, the estimated * volume | |
| | of gas to be flared is120MC | F; Value | |
| C. | Name and location of nearest gas gathering facility: | | |
| | Frac Cat Compressor Station, Lea County, NM | | |
| D. | DistanceEstimated cost of connection | | |
| E. | This exception is requested for the following reasons: <u>Intermittent curtailment by Agave due to</u> | | |
| | compressor maintenance and high line pressure. Well shut in at this time may damage formation and reduce future production. | | |
| | | | |
| OPERATOR OIL CONSERVATION DIVISION. | | | |
| II I will died the land of the City of the | | , | |
| Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief. | | Approved Until 3/1/2016 | |
| Signature | | By Majeys Brown | |
| Printed Name | | Title | |
| & Title <u>Gary Cooper, Vice President Operations</u> | | 12/0/2011 | |
| Email Address rcooper@jdmii.com | | Date 12/9/2019 | |
| Date 12/01/15 Telephone No. 972-931-0700 | | | |

^{*} Gas-Oil ratio test may be required to verify estimated gas volume.