

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

SEP 09 2015

BRADENHEAD TEST REPORT

RECEIVED

Operator Name Chevron USA Inc.	API Number 30-025-35953
Property Name New Mexico SA State	Well No. 112

7. Surface Location

UL - Lot B	Section 24	Township 18S	Range 37E	Feet from 330	N/S Line N	Feet From 1733	E/W Line E	County LEA
---------------	---------------	-----------------	--------------	------------------	---------------	-------------------	---------------	---------------

Well Status

Well Status	SHUT-IN	PRODUCING Oil	DATE 8/29/15	75
-------------	---------	------------------	-----------------	----

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure		120			
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks: INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Failure

Signature: Diego Juarez	OIL CONSERVATION DIVISION
Printed name: Diego Juarez	Entered into RBDMS BS
Title: FS A	Re-test
E-mail Address: FDMK@chevron.com	
Date: 8/29/15	Phone: 325-242-3435
Witness:	

BS 11/2/16

JAN 12 2016