Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NMOCD Hobbs

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	Expires. Ju
5.	Lease Serial No.
	NMNM16835

SUNDRY N	OTICES	SAND	REPO	RTS (ON W	ELLS	
Do not use this	form for	propo	sals to	drill o	r to n	e-enter	an
abandoned well	Hee for	m 316	0-3 /AP	D) for	euch	nronos	sales

6. If Indian, Allottee or Tribe Name

FEB 2 3 2016

2. Name of Operator CHEVRON USA INCORPORATED E-Mail: leakejd@chevron.com 3a. Address 15 SMITH ROAD MIDLAND, TX 79705 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 14 T20S R35E NWNE 660FNL 1650FEL 32.578634 N Lat, 103.424725 W Lon 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION NEUHAUS 14 FED 02 NEUHAUS 14 F	SUBMIT IN TRIPLICATE - Other instructions on reverse side S									
CHEVRON USA INCORPORATED E-Mail: leakejd@chevron.com 30-025-31970-00-S2 3a. Address 15 SMITH ROAD MIDLAND, TX 79705 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 14 T20S R35E NWNE 660FNL 1650FEL 32.578634 N Lat, 103.424725 W Lon 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION TYPE OF ACTION TYPE OF ACTION	1. Type of Well Gas Well Other Gas Well Other									
15 SMITH ROAD MIDLAND, TX 79705 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 14 T20S R35E NWNE 660FNL 1650FEL 32.578634 N Lat, 103.424725 W Lon 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION TYPE OF ACTION TYPE OF ACTION	2. Name of Operator CHEVRON USA INCORPORATED E-Mail: leakejd@chevron.com Contact: DENISE PINKERTON 30-025-31970-00-S2									
Sec 14 T20S R35E NWNE 660FNL 1650FEL 32.578634 N Lat, 103.424725 W Lon 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION	3b. Phone No. (include fractions) Ph: 432-687-7375	To the same a confict confict many								
32.578634 N Lat, 103.424725 W Lon 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION Type of Action										
TYPE OF SUBMISSION TYPE OF ACTION Decrease Dec										
D Acidiza Deepen D Production (Start/Recume) D Water Shut, Off	12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA									
□ Acidize □ Deepen □ Production (Start/Resume) □ Water Shut-Off	TYPE OF A	CTION								
Notice of Intent	□ Deepen	☐ Production (Start/Resume) ☐ Water Shut-C	off							
☐ Alter Casing ☐ Fracture Treat ☐ Reclamation ☐ Well Integrity	sing Fracture Treat	☐ Reclamation ☐ Well Integrity	/							
Subsequent Report	Repair New Construction	□ Recomplete □ Other								
☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon ☐ Temporarily Abandon	Plans Plug and Abandon	▼ Temporarily Abandon								
☐ Convert to Injection ☐ Plug Back ☐ Water Disposal	to Injection Plug Back	☐ Water Disposal								
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) CHEVRON U.S.A. INC. INTENDS TO TEMPORARILY ABANDON THE SUBJECT WELL. THE WELL IS UNECONOMICAL TO PRODUCE AT THIS TIME AND WE HAVE IDENTIFIED UPHOLE POTENTIAL IN THE BONE SPRING (SEE ATTACHED GEOLOGIC REVIEW) OUR RIG QUEUE IS SUCH THAT WE WILL NOT BE ABLE TO GET TO THIS WELL UNTIL MID 2016, THUS WE ARE ASKING FOR A 1 YR TA STATUS. PLEASE FIND ATTACHED, THE WELLBORE DIAGRAMS, AND GEOLOGIC REVIEW. ANY QUESTIONS/CONCERNS SHOULD BE ADDRESSED TO MICHAEL STAFF, CHEVRON PETRO ENGINEER AT 432-687-7126. DURING THIS PROCESS WE PLAN TO USE THE CLOSED LOOP SYSTEM WELLS TAKE THE TANK AND HAUL TO THE CONDITIONS OF APPROVAL. 14. I hereby certify that the foregoing is true and correct.										
Electronic Submission #295899 verified by the BLM Well Information System For CHEVRON USA INCORPORATED, sent to the Hobbs Committed to AFMSS for processing by LINDA JIMENEZ on 05/05/2015 (15LJ1129SE) Name(Printed/Typed) DENISE PINKERTON Title REGULATORY SPECIALIST										
Signature (Electronic Submission) Date 03/24/2015										
THIS SPACE FOR FEDERAL OR STATE OFFICE USE										
Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Fitle 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the finited States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.										

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

MUB/00 2/22/2014

Additional data for EC transaction #295899 that would not fit on the form

32. Additional remarks, continued

REQUIRED DISPOSAL, PER THE OCD RULE 19.15.17.

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 12 months ending 02/12/2017 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

NEUHAUS 14 Fed 2

- 1. Well is approved to be TA/SI for a period of 12 months or until 02/12/2017
- 2. This will be the last TA approval for this well.
- 3. Must submit NOI to recomplete or NOI to P&A. Must be submitted by 02/12/2017
- 4. COA's met at this time.