FEB 2 3 2016	State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office							
RECEIVED	BI	RADENI	HEAD TES	T REPORT	C			
Churron (	Operator Name							
Vacuum Graybu	Property Name lacunar Grayburg San Andres Unit					Well No.		
	5	7. Su	irface Location	n				
UL-Lot Section Township K 1 1§ 5	Range 34 E		Feet from	N/S Line	Feet From	E/W Line E	County	
March March 2017		V	Vell Status	30 1				
TA'D WELL	SHUT-IN		INJECTOR		PRODUCER		DATE	
YES NO YE		INJ	and the second se	WD OR	PRODUCER	s 21231	DATE	

## OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	6	Alex Martine	Salar and	35	580
Flow Characteristics					
Puff	Y/O	Y / N	Y / N	Y / N	CO2
Steady Flow	Y/O	Y / N	Y/N	Y / N	WTR_
Surges	Y/O	Y/N	Ŷ/N	Y / N	GAS
Down to nothing	Ø/N	Y / N	Y / N	Y / N	Injected for
Gas or Oil	Y/O	Y/N	Y / N	Y/N	Waterflood if applies.
Water	Y/(N)	Y / N	Y/N	Y/N	-

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or co	ontinuous build up if applies.			
1 0 1	B8 2/24/10			
Signature:	OIL CONSERVATION DIVISION			
Printed name: ACEX ORMSB1	Entered into RBDMS	CF		
Title: Field Specialist	Re-test			
E-mail Address: EBXF@ Cherron. con				
Date: 2(23/2016 Phone: 20 (575) 513-5521		all where		
Witness: Crand Flowed		1 1 1 1 1 1 1 1 1		

FEB 2 5 2016

In C.F.