


District I
 1625 N. French Dr., Hobbs, NM 88240
 Phone: (575) 393-6101 Fax: (575) 393-0720



State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name ✓ Chevron USA							API Number 30-025-31132			
Property Name ✓ Vacuum Gabriela West Unit							Well No. 114 H			
7. Surface Location										
UL - Lot B	Section 1	Township 18 S	Range 34 E	Feet from 280	N/S Line N	Feet From 2080	E/W Line E	County hca		
Well Status										
TA'D WELL YES	<input checked="" type="radio"/> NO	YES	SHUT-IN <input checked="" type="radio"/> NO	INJ	INJECTOR SWD	<input checked="" type="radio"/> OIL	PRODUCER GAS	DATE 2/24/16		

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csg	(E)Tubing
Pressure	\emptyset	\emptyset		20	90
Flow Characteristics					
Puff	Y / <input checked="" type="radio"/> N	<input checked="" type="radio"/> Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / N	WTR ___
Surges	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / N	GAS ___
Down to nothing	<input checked="" type="radio"/> Y / N	<input checked="" type="radio"/> Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Injected for
Water	Y / <input checked="" type="radio"/> N	Y / <input checked="" type="radio"/> N	Y / N	Y / N	Waterflood if applies

Remarks – Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature:	BS 2/25/16	
Printed name: Ruben Rodriguez	OIL CONSERVATION DIVISION	
Title: Field Specialist	Entered into RBDMS	CF
E-mail Address:	Re-test	
Date: 2-24-16	Phone: 575-513-5526	
	Witness: Carol Flowers	

FEB 26 2016