## HOBBS OCD

## MAR 1 1 2016

## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office

Oil Conservation Division Hobbs District Office

BRADENHEAD TEST REPORT

Operator Name
Chevron

OSA

OFFICE OFFICE

			Operator Name Chevron	USA INC	_ <		30-025- Z	5729
Property Name  Central Vacuum Unit								No.
				7. Surface Location	on			
UL - Lot	Section 31	Township 175	Range <b>35</b> E	Feet from 2561	N/S Line	Feet From	E/W Line	County \ Lea \
				Well Status				
YES TA'D	WELL 6	yes	SHUT-IN	INJECTOR INJECTOR	SWD OIL	PRODUCER GAS	22	DATE 23-16

## **OBSERVED DATA**



	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	D	NA	NA	0	1650
Flow Characteristics					
Puff	Y/62	Y / N	Y / N	Y / 🔊	C02 <u>K</u>
Steady Flow	Y / 🚫	Y/N	Y / N	Y/60	GAS WTR_X
Surges	Y / Ø	Y / N	Y / N	Y/Ø	Type of Fluid
Down to nothing	Ø/ N	Y / N	Y / N	Ø/ N	Injected for
Gas or Oil	Y/0	Y / N	Y / N	Y / 🔊	Waterflood if applies.
Water	Y/W	Y / N	Y/N	Y/(V)	

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

		BS 3/11/16		
Signature:		OIL CONSERVATION DIVISION		
Printed name: Tanner DeHaan		Entered into RBDMS		
Title: FSA		Re-test		
E-mail Address: TZYR@Chevron.	com			
Date: 2-23-16	Phone: 575-390-4449			
	Witness:			