District I 1625 N. French Dr Phone (575) 393-6			State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office BRADENHEAD TEST REPORT					HOBBS OCD MAR 1 1 2016 RECEIVED	
					USA IN		34		
		S. Sect.	and and a second se	7.	Surface Locatio	on		S. S. A.	State A. A.
UL - Lot	Section 6	Township 185	Range 35 <i>E</i>		Feet from	N/S Line	Feet From 1040	E/W Line	County Lea
				2.00	Well Status				- 1-27
TA'D YES	WELL	9 YES	SHUT-IN	0 6	INJECTOR	SWD OIL	PRODUCER GAS	2.2	date 2 6 - 16

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	6	0	0	0	1890
Flow Characteristics					
Puff	Y/00	()/ N	Y / O	O/N	CO2
Steady Flow	YIO	Y/O	Y / Ø	Y/00	
Surges	Y/O	Y/O	Y/O	¥ / (3)	GAS
Down to nothing	00/ N	O/N	Ø/ N	Ø/ N	Injected for
Gas or Oil	Y/OP	Y/Ø	Y / Ø	Y / 🕑	Waterflood if applies.
Water	Y/O	Y/O	Y/O	Y/ 🔊	

Signature:	OIL CONSERVATION DIVISION
	B& 3-11-16

Title: FSA		Re-test		
E-mail Address: TZYR@Chevron	.com			
Date: 2-26-14	Phone: 575-390-4449			
	Witness:			

INSTRUCTIONS ON BACK OF THIS FORM