

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-06632
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Apache Corporation		6. State Oil & Gas Lease No. BO-8105
3. Address of Operator 303 Veterans Airpark Lane, Suite 1000 Midland, TX 79705		7. Lease Name or Unit Agreement Name West Blinbry Drinkard Unit (WBDU) / 37346
4. Well Location Unit Letter O : 660 feet from the South line and 1980 feet from the East line Section 16 Township 21S Range 37E NMPM County Lea		8. Well Number 088
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3451' GL		9. OGRID Number 873
		10. Pool name or Wildcat Eunice; B-T-D, North (22900)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐
OTHER: CASING LEAK REPAIR ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Apache found and repaired a casing leak, as follows:

1/18/2016 MIRUSU POOH w/prod equip.
1/19/2016 RIH w/scrapper. RIH w/pkr & plug; set plug @ 5510'. Tested plug to 800#; no leaks.
1/20/2016 Isolated casing leak from 4393'-4426', spotted 150# sand thru tbg on plug. POOH w/pkr & RIH w/cmt retainer.
1/21/2016 Test lines to 3000#. Pump 48 bbls 14.8# cement, flush. Pressure up to 2500#, sting out of cmt ret. Recovered 20 bbls cmt. Flushed w/120 bbls flush. WOC to dry.
1/22/2016 DO cmt retainer; tag cmt @ 4228'.
1/25/2016 Circ clean. Tested csg to 300# for 30 min. - no loss. Wash sand off RBP @ 5510'; release plug.
1/26/2016 LD WS & RBP. Tested 2-3/8" tbg in hole; tested good. Tag @ 6275'; TAC @ 5351'; SN @ 6250'.
1/27/2016 RIH w/rods & pump. Test to 500#; hung well on. POP

Spud Date:

5/13/1947

Rig Release Date:

6/12/1947

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Reesa Fisher

TITLE Sr. Staff Reg Analyst

DATE 1/28/2016

Type or print name Reesa Fisher

E-mail address: Reesa.Fisher@apachecorp.com

PHONE: (432) 818-1062

For State Use Only

APPROVED BY:

[Signature]

TITLE

Petroleum Engineer

DATE

07/24/16

Conditions of Approval (if any):

MAR 25 2016