

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

HOBBS OCD

MAR 28 2016

BRADENHEAD TEST REPORT

RECEIVED

Operator Name CHEVRON USA INC ✓	API Number 30-025-24364 ✓
Property Name Vacuum Cracking SAN Andre Unit ✓	Well No. 46 ✓

7. Surface Location

UL - Lot H	Section 2	Township T18S	Range R34E	Feet from 1405	N/S Line FNL	Feet From 1230	E/W Line FEL	County LEA ✓
----------------------	---------------------	-------------------------	----------------------	--------------------------	------------------------	--------------------------	------------------------	------------------------

Well Status

Well Status	SHUT-IN	PRODUCING In	DATE 3/15/2016
-------------	---------	------------------------	--------------------------

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

OBSERVED DATA

If bradenhead flowed water, check all of the descriptions that apply:

	(A)Surf-Interm	(B)Interm(1)-Interm(2)	(C)Interm-Prod	(D)Prod Csgng	(E)Tubing
Pressure	Ø	—	—	Ø	1960 wtr
Flow Characteristics					
Puff	Y/N	Y / N	Y / N	Y / N	
Steady Flow	Y / N	Y / N	Y / N	Y / N	
Surges	Y / N	Y / N	Y / N	Y / N	
Down to nothing	Y / N	Y / N	Y / N	Y / N	
Gas or Oil	Y / N	Y / N	Y / N	Y / N	
Water	Y / N	Y / N	Y / N	Y / N	

If bradenhead flowed water, check all of the descriptions that apply:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

Remarks:

INJECTING AT THIS TIME ___ WTR, ___ GAS, ___ CO2

Failed mit - would not hold pressure - Rule - 19.15.26.11.

gmb

BS 4/1/16

Signature: Eddie Gallegos	OIL CONSERVATION DIVISION
Printed name: EDDIE GALLEGOS	Entered into RBDMS CB
Title: SSPS	Re-test
E-mail Address: eiv@chevron.com	
Date: 3/15/16	Phone: 575-631-8516
Witness: [Signature]	

APR 04 2016