	Submit One Copy To Appropriate District Office State of New Mexico	Form C-103	
	District I Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.	
	District II 811 S. First St., Grand Ave. Ariesia, NM OIL CONSERVATION DIVISION	30-025-20232	
	88210 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE X FEE	
	1000 Rio Brazos Rd., Aztec, NM 87410 Salita Fe, NW 67505	6. State Oil & Gas Lease No.	
	District IV 1220 S. St. Francis Dr., Santa Ferre CEIVED 87505	B-1400-11	
[87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	VACUUM GLORIETA EAST UNIT TRACT 06	
	1. Type of Well: XOil Well Gas Well Other	8. Well Number 001	
	2. Name of Operator ConocoPhillips Company	9. OGRID Number 217817	
	3. Address of Operator P. O. Box 51810 Midland, TX 79710	10. Pool name or Wildcat VACUUM; GLORIETA	
	4. Well Location	,	
	Unit Letter J : 2310 feet from the SOUTH and 1980 feet from the EAST ine		
Section 33 Township 17S Range 35E NMPM County LEA 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3956' GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		ata	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		SEQUENT REPORT OF:	
1	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK		
	TEMPORARILY ABANDON	_	
		Du	
OTHER: Location is ready for OCD inspection after P&A \ \ \ \ \ \ \ \ \ \			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
	OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
	UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
-	The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment.		
	Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
	If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed		
	from lease and well location.		
[All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)		
	X All other environmental concerns have been addressed as per OCD rules.		
	Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.		
1	etrieved flow filles and pipelifies.		
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
1	GIGNATURE CHONSIA TITLE Staff Regulatory Techn	DATE <u>03/31/2016</u>	
	TYPE OR PRINT NAME Rhonda Rogers E-MAIL: rogerrs@conocophi	illips.com PHONE: <u>(432)688-9174</u>	
Ī	For State Use Only		
	APPROVED BY: Washer tolen_ TITLE P.E.S.	DATE 4-19-2016	
(Conditions of Approval (if any):		

APR 2 1 2016