

APR 27 2016
RECEIVED

## State of New Mexico

## **Energy, Minerals and Natural Resources Department Oil Conservation Division Hobbs District Office**

BRADENHEAD TEST REPORT

Chevron USA, LLC.							API NUMBER 30-025- 22382 Well No.		
			7. Su	rface Locatio	n				
J Section Township 225				Feet from	N/S Line Feet 19			E/W Line <b>E</b>	County L&A
			V	Vell Status					
Well Status		SHUT-IN		PRODUCING		DATE 4-14-16			,
bradenhead flo		RADENHEAD AND IN check all of the descript	OBS	O ATMOSPHER SERVED DAT		LLY FOR 15	MINUT	ES EACH	00
		(A)Surf-Interm	(B)Interm(1)-Interm(2)		(C)Interm-Prod		(D)Prod Csng		(E)Tubing
Pressure		0	NA		NA		26		125
Flow Characteristics			,.,						/
Puff		Y / 60			Y /		Y / N		
Steady Flow		Y / 60			Y/N			Y/N	
Surges		Y / 🚫	Y/N		Y / N			Y/N	
Down to nothing  Gas or Oil		Y/(8)	Y / N Y / N		Y / N Y / N		Y/N Y/N		
Water		Y / 🔯	Y/N		Y/N		Y/N		
bradenhead flo	owed water,	check all of the descript	ions that apply:	TY:	SUL	FUR:		BLACK:	
Remarks:					INJECTING A	T THIS TIM	Е	WTR,	GAS,CO2
Signature		Joseph Col	lins			OII	B	8 4 28	
		Joseph Col	Vlins			-		SERVATION	N DIVISION
Printed name:	Josep	h Collins				Entered		SERVATION	
Printed name:	Josep Produ	h Collins action Specialist Su				-		SERVATION	
Signature: Printed name: Title: E-mail Address Date: 4-/	Josep Produ	h Collins action Specialist Su asJ@chevron.com				Entered		SERVATION	