	Submit 1 Copy 10 Appropriate District  Office  District I  1625 N. French Dr., Hobbs, NM 88240  District II		Form C-103 October 13, 2009	
			WELL API NO.	
	OII CONSEDVATION	DIVISION	30-025-28468	
	District III	ncis Dr.	5. Indicate Type of Lease STATE FEE	
	Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
	District IV 1301 W. Grand Ave., Artesia, NM 88210 13 2012 20 South St. Francis Dr. 13 2012 20 South St. Francis Dr. Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505		VA-928	
9	SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name	
	PROPOSALS.)		State NO  8. Well Number 1	
	1. Type of Well: Oil Well Gas Well Other SWD		o. Well Number	
	. Name of Operator Basic Energy Services, LP		9. OGRID Number 246368	
	. Address of Operator .O Box 10460 Midland Tx, 79702		10. Pool name or Wildcat SWD Deleware	
	4. Well Location			
			60 feet from the W line	
	11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
			SEQUENT REPORT OF:	
	PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK			
	TEMPORARILY ABANDON			
			⊺JOB □	
	DOWNHOLE COMMINGLE			
	OTHER	OTHER:		
-	13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.  5-18-16 Pumped 800 gal 15% NEFE down tbg. Displaced with 40 Bbl. F/water SDFN  5-20-16 Pumped 40 Bbl. w 10 gal surfactant and 10 gal.			npletions: Attach wellbore diagram of	
			Pumped 40 Bbl. w 10 gal surfactant and 10 gal of	
	<ul> <li>Scale Inhibitor SDFN 5-23-16 MIRSU and equipment call in for Kill mud SDFN.</li> <li>5-24-16 Pumped 50 Bbl. 13# down tbg. Released Pkr. Pumped 70 Bbl. 13# down annulus TOH w/ Tbg. laid 31 bad joints and 84 stands in derrick used 15# mud to displace tbg. Capacity in casing. Sent in 5 ½ x 2 7/8 Arrow set for redress SDFN.</li> <li>5-26-16 RU snubbing Unit waiting on working string. SDFN</li> <li>5-27-16 TIH W/4 ¾ bit and scrapper to 7248' working Csg. 200' above top Perf. @ 6409' TOH with bit and scrapper to 6200' SDFN.</li> <li>5-31-16</li> </ul>			
TOH with w/s laying down call in for Hydro-Testers and Scan log SDFN. 6-1-16 TIH with pipe in derrick scanned all bad - laid down wait in new string.SDFN 6-2-16 Tally new 2 7/8 J-55 TIH with Pkr. and 195 joints set Pkr.@ 6363' Loaded tbg with F/W PSI on annulus to 700 # psi good disengaged O/0				
				<ul> <li>tool and started circulating 3% Pkr. fluid to frac tank. Pkr Jumped called for Snubbing. SDFN</li> <li>6-3-16 RIH with collar locator logged below Pkr. Confirmed that packer is on O/O tool TIH with 2.25 blanking plug and set. SDFN. 6-6-16 NU Snubbing unit TOH with Pkr. Sent Packer in for reason why it jumped found trash on mandrel and slips nubs broken replaced element also. 6-7-16 Snubbing Unit breaks down SDFN.</li> <li>6-9-16 TIH with 194 joints Pkr. set at 633' left one joint out. Test casing MIT Held 700 psig for 30 min ND Snubbing unit call in for OCD MIT</li> </ul>
Released all Equipment.  6-13-16 MIT failed had 500 psi on casing sent C-103 intent to pull into the Pkr. element.			1 30 mm 1 10 Gradonig and can in for GCD 1411	
S	pud Date: Rig Release Da	ate:		
_				
I	I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
S	SIGNATURE David H. Alvarado TITLE SENM District Fluid Sales Mgr. DATE 6/13/16			
Т	Type or print name DAVID H. ALVARADO E-mail address: david.alvarado@basicenergyservices.com PHONE: 575.746.9663			
	For State Use Only  APPROVED BY:  Conditions of Approval (if any):  Accepted for Record Only  ACCEPTED TITLE  DATE			
9	Accepted for Rece	Me diny	D. 1	
	PPROVED BY: Conditions of Approval (if any):	2/2/01/-	DATE	
ME WILL COLLE				