Submit 3 Copies To Appropriate District Office State of	New Mexico		Form C-103	
	State of New Mexico Energy, Minerals and Natural Resources		WELL API NO.	
1625 N. French Dr., Hobbs, NM 88240		30-025-05974		
District II 1301 W. Grand Ave., Artesia, NM 88210  DISTRICT II 1301 W. Grand Ave., Artesia, NM 88210		5. Indicate Type of Lease		
Diertict III				
011 011 71116	St. Francis Dr.	STATE		
District IV  1220 S. St. Francis Dr., Santa Fe, NM  Santa Fe, NM  Santa Fe, NM  Santa Fe, NM		6. State Oil & Gas Lease No.		
87505 RECEIVED	100			
SUNDRY NOTICES AND REPORTS ON W		7. Lease Name or Unit A	greement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR DEEPEN OR PLUG BACK TO		Bertha J Barber		
A DIFFERENT RESERVIOR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		8. Well Number		
1. Type of Well: Oil Well Gas Well Other		2 vveii Number		
2. Name of Operator		9. OGRID Number		
Apache Corporation		873		
3. Address of Operator		10. Pool Name		
303 Veterans Airpark Ln., Ste. 3000, Midland,	TX, 79705	Eunice Mon	ument G/SA	
4. Well Location  Unit Letter A: 330 feet from th	e <b>N</b> line and	990 feet from the	E line	
Section 7 Township 20S			County Lea	
11. Elevation (Show whethe				
	3574' GL			
12. Check Appropriate Box To Indicate Nature of Notice, Rep	ort, or Other Data			
PERFORM REMEDIAL WORK PLUG AND ABANDON CHANGE PLANS PULL OR ALTER CASING MULTIPLE COMPL DOWNHOLE COMMINGLE  OTHER:  All pits have been remediated in compliance with OCD rules and the telement of the complex of the co	rms of the Operator's pit perm oles have been properly aband I has been set in concrete. Its	eady for OCD inspection affities and closure plan. doned. shows the	ter P&A Pm	
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER / QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. ALL INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
The location has been leveled as nearly as possible to the original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.				
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed				
from the lease and well location.				
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have				
to be removed.)  All other environmental concrens have been addressed as per OCD rules.				
All other environmental concrens have been addressed as per OCD rules.  Pipelines and flow lines have been abandoned in accordance with 19.15.9.714.B(4)(b) NMAC. All fluids have been removed from				
non-retrieved flow lines and pipelines.	( )/( ) /			
When all work has been completed, return this form to the appropriate inspection has to be made to a P&A location because it does not meet		-		
O IN	the oftena above, a penalty in	lay be assessed.		
SIGNATURE TITLE	P&A Technici	an DATE	6/27/16	
TYPE OR PRINT NAME Leon Sellers	leon.sellers@apache	corp.com PHONE:	432-208-0349	
For State Use Only			1 1	
N. 01 V. 1	P.E.S.	DATE	7/5/2014	
APPROVED BY: TITLE  Conditions of Approval (if any):		DATE	11-12010	