

AUG 08 2016

State of New Mexico
Energy, Minerals and Natural Resources Department
Oil Conservation Division Hobbs District Office

AUG 08 2016

RECEIVED

BRADENHEAD TEST REPORT

RECEIVED

Operator Name DKD, LLC		*API Number 30-025-27886
Property Name Richardson Fee SWD		Well No. 2

7. Surface Location

UL - Lot K	Section 5	Township 14S	Range 36E	Feet from 1980	N/S Line S	Feet From 1980	E/W Line W	County Lea
----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	--------------------------	----------------------	----------------------

Well Status

YES	TA'D WELL NO	YES	SHUT-IN NO	INJ	INJECTOR SWD	OIL	PRODUCER	GAS	DATE 7-27-16
-----	------------------------	-----	----------------------	-----	------------------------	-----	----------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Casing	(E)Tubing
Pressure	0	0	0 NA	0	0 (SLIGHT VAC)
Flow Characteristics					
Puff	Y/N	Y/N	Y/N	Y/N	CO2 —
Steady Flow	Y/N	Y/N	Y/N	Y/N	WTR X
Surges	Y/N	Y/N	Y/N	Y/N	GAS —
Down to nothing	Y/N	Y/N	Y/N	Y/N	Type of Fluid
Gas or Oil	Y/N	Y/N	Y/N	Y/N	Injected for
Water	Y/N	Y/N	Y/N	Y/N	Waterflood if applies

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

(C) Puff 15 seconds; no water

Signature: Danny R Watson		OIL CONSERVATION DIVISION	
Printed name: DANNY R WATSON		Entered into RBDMS MAK 8/8/2016	
Title: OWNER		Re-test	
E-mail Address:			
Date: 7/27/16	Phone: 575-369-5024		
Witness: NA			

INSTRUCTIONS ON BACK OF THIS FORM