

State of New Mexico
 Energy, Minerals and Natural Resources Department
 Oil Conservation Division Hobbs District Office

AUG 31 2016

RECEIVED

BRADENHEAD TEST REPORT

Operator Name APACHE CORP		API Number 30 025 06444	
Property Name WEBDU		Well No. 9	

7. Surface Location

UL - Lot 14	Section 9	Township 21S	Range 37E	Feet from 1980	N/S Line N	Feet From 660	E/W Line E	County LEA
-----------------------	---------------------	------------------------	---------------------	--------------------------	----------------------	-------------------------	----------------------	----------------------



Well Status

TA'D WELL YES	NO	SHUT-IN NO	NO	INJECTOR INJ	SWD	PRODUCER OIL	GAS	DATE 8-30-16
-------------------------	-----------	----------------------	-----------	------------------------	-----	------------------------	-----	------------------------

OBSERVED DATA

	(A)Surface	(B)Interm(1)	(C)Interm(2)	(D)Prod Csng	(E)Tubing
Pressure	ϕ		ϕ	ϕ	ϕ
Flow Characteristics					
Puff	Y / N	Y / N	Y / N	Y / N	CO2 ___
Steady Flow	Y / N	Y / N	Y / N	Y / N	WTR ___
Surges	Y / N	Y / N	Y / N	Y / N	GAS ___
Down to nothing	Y / N	Y / N	Y / N	Y / N	Type of Fluid
Gas or Oil	Y / N	Y / N	Y / N	Y / N	Injected for
Water	Y / N	Y / N	Y / N	Y / N	Waterflood if applies.

Remarks - Please state for each string (A,B,C,D,E) pertinent information regarding bleed down or continuous build up if applies.

Signature: 	OIL CONSERVATION DIVISION
Printed name: DAVID CUMMINGS	Entered into RBDMS
Title: SR PUMPER	Re-test 
E-mail Address:	
Date:	Phone:
	Witness: