Submit One Copy To Appropriate District Office	State of New Me		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natur	ral Resources	WELL API NO.
District II 811 S First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-025-10976
District III	1220 South St. Fran	icis Dr.	5. Indicate Type of Lease STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87	505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			B-9974
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name MYERS LANGLIE MATTIX UNIT
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		OCD	8. Well Number
2. Name of Operator OXY USA WTP LP	AUG 2 9	2016	9. OGRID Number 192463
3. Address of Operator PO BOX 4294; HOUSTON, TX 777	210 RECEI	VFD	10. Pool name or Wildcat LANGLIE MATTIX 7RVR QN-GB
4. Well Location	NEVE	W los lo	/
Unit Letter N : 660 feet from the SOUTH line and 1980 feet from the WEST line			
Section 2 Township 24S Range 37E NMPM County LEA			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
3221' 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF IN			SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DR		REMEDIAL WORK	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	The state of the s
			Pa V
OTHER: \(\subseteq \) Location is ready for OCD inspection after P&A \(\subseteq \) All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.			
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR			
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and			
other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.			
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed			
from lease and well location. All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have			
to be removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.			
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well			
location, except for utility's distribution infrastructure.			
When all work has been completed, return this form to the appropriate District office to schedule an inspection.			
SIGNATURE			
TYPE OR PRINT NAME _CASEY L SUMMERS _ E-MAIL: _casey_summers@oxy.com _ PHONE: _575-513-8289			
Me Carla DES			
APPROVED BY:			