Submit One Copy To Appropriate District Office	State of New Me		Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natu	Iral Resources	Revised November 3, 2011 WELL API NO.
District II 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	and a second	30-025-26058 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Fran		STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 8	/505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name MYERS LANGLIE MATTIX UNIT
PROPOSALS.) 1. Type of Well: XOil Well	HORD	SOCD	8. Well Number 147
2. Name of Operator	AUG 2	0.2040	9. OGRID Number
OXY USA WTP LP 3. Address of Operator	AUG 2	J 2016	192463 10. Pool name or Wildcat
PO BOX 4294; HOUSTON, TX 7	7210 RECE	IVED	LANGLIE MATTIX 7RVR QN-GB
4. Well Location			
Unit Letter_F : 1980 feet from the NORTH line and 1980 feet from the WEST line			
Section <u>4</u> Township	24S Range <u>37E</u> NMPM 11. Elevation (Show whether DR		
	326	54'	
12. Check Appropriate Box to	o Indicate Nature of Notice, R	eport or Other D	ata
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR			LLING OPNS. P AND A
PULL OR ALTER CASING		CASING/CEMENT	гјов
OTHER:			eady for OCD inspection after P&A / PM
 All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the 			
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
 The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and other production equipment. Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level. If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with 			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.			
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)			
 All other environmental concerns have been addressed as per OCD rules. Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines. 			
		ical service poles and	d lines have been removed from lease and well
When all work has been completed,	return this form to the appropriate	District office to sch	edule an inspection.
SIGNATURE		ENVIRONMENTAI	LADVISOR_DATE 8-29-16
TYPE OR PRINT NAME _CASEY	L SUMMERSE-MAIL:	ey summers@oxy.co	om PHONE: _575-513-8289
APPROVED BY:	etitale	P.E.S.	DATE 9/7/2016
Conditions of Approval (if any):			
			and the second second
			ſ