District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Energy Mineral Cons 1220 Sou Santa 2016	of New Mexico is and Natural Res ervation Division of St. Francis Dr. Fe, NM 87505 NF		Form C-129 Revised August 1, 2011 Submit one copy to appropriate District Office (For Division Use Only)	
APPLICATION FOR EXCEPTION TO NO-FLARE RULE 19.15.18.12					
(See Rule 19.15.18.12 NMAC and Rule 19.15.7.37 NMAC)					
A. Applicant <u>Murchison Oil &</u>	k Gas, Inc.			,	
whose address is7250 Dal	whose address is7250 Dallas Parkway, Ste. 1400, Plano, TX 75024,				
hereby requests an exception to Rule 19.15.18.12 for days or until <u>January 7</u> ,					
, Yr <u>2017</u> , for the following described tank battery (or LACT):					
Name of Lease Jackson Unit 19H (30-025-41138) Name of Pool Triple X; Bone Spring, West					
Location of Battery: Unit Letter <u>N</u> Section <u>21</u> Township <u>24S</u> Range <u>33E</u>					
Number of wells producing into battery1					
B. Based upon oil production of	Based upon oil production of <u>62</u> barrels per day, the estimated * volume				
of gas to be flared is90	of gas to be flared isMCF; Value\$225per day.				
C. Name and location of nearest g	Name and location of nearest gas gathering facility:				
Frac Cat Compressor Station,	Frac Cat Compressor Station, Lea County, NM				
D. Distance	DistanceEstimated cost of connection				
E. This exception is requested for the following reasons: <u>Intermittent curtailment by Agave due to</u> <u>compressor maintenance</u> . Well shut in at this time may damage formation and reduce future production.					
OPERATOR	O	OIL CONSER	VATION DIVIS	SION	
I hereby certify that the rules and regulations of the Oil Conservation Division have been complied with and that the information given above is true and complete to the best of my knowledge and belief.		Approved Unt	il <u>1/7</u>	2017	
Signature		By	Mapyst	Snown	
Printed Name & Title <u>Gary Cooper</u> , Vice President Operations		Title	0		
Email Address rcooper@jdmii.com		Date	9/20	9/2016	
Date 9/23/16 Telephone No. 972-931-07	00			-	

* Gas-Oil ratio test may be required to verify estimated gas volume.