Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR HOBBS OF DATA OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-entert Sbad

Tice

o. If Indian, Allottee or Tribe Name

of the Company of the Co

RSUBMETINTEIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well					8. Well Name and No.		
☑ Oil Well ☐ Gas Well ☐ Other					8115 JV-P MESA B 3H		
2. Name of Operator Contact: KAYLA MCCONNELL BTA OIL PRODUCERS E-Mail: kmcconnell@btaoil.com					9. API Well No. 30-025-42126-00-X1		
3a. Address 104 SOUTH PECOS STREET MIDLAND, TX 79701 3b. Phone No. Ph: 432.68			(include area code 2.3753			Exploratory 53329D	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, and State		
Sec 7 T26S R33E SWSE 190 32.051182 N Lat, 103.609404	LEA COUNTY, NM						
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF	NOTICE, R	EPORT, OR OTHER	RDATA	
TYPE OF SUBMISSION			F ACTION				
Notice of Intent ☐ Acidize		☐ Deepen ☐ Produ			tion (Start/Resume)		
	☐ Alter Casing	ter Casing		ation	■ Well Integrity		
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	□ Recom	plete	⊘ Other	
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	and Abandon	☐ Tempo	rarily Abandon	Change to Original A PD	
	☐ Convert to Injection	Plug	Back	☐ Water	Disposal		
following completion of the involved testing has been completed. Final Al determined that the site is ready for f BTA Oil Producers, LLC responsional approved APD. A variance is requested for the Choke Hose -See attached test chart and s Multi bowl Wellhead -Wellhead will be installed on	pandonment Notices shall be file inal inspection.) ectfully request approval for the following items listed belongers. specs. a 13-3/8" casing and tester	or the following ow:	equirements, including drilling change EE ATTA	ding reclamation des to the ACHED ONS OF	FOR APPROVAL	and the operator has	
	Electronic Submission #3	IL PRODUCE	RS, sent to the	Hobbs			
Name (Printed/Typed) KAYLA MCCONNELL			Title PRODUCTION ASSISTANT				
Signature (Electronic S	Submission)		Date 08/02/2	2016			
1 947	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE U	SE		
Approved By (BLM Approver Not	Specified) Mustafa 1	Jague.	Title	PETROLE	JM ENGINEER	Date 09/21/2016	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Hobbs				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s					ake to any department or	agency of the United	

Additional data for EC transaction #346496 that would not fit on the form

32. Additional remarks, continued

30 days between test. If any seal subject to testing is broken the system will be retested. Manufacturer representative will be present for install.

-See attached Schematic.

PECOS DISTRICT CONDITIONS OF APPROVAL

OPERATOR'S NAME:

BTA Oil Producers

LEASE NO.:

NM0160973

WELL NAME & NO.:

3H-8115 JV-P Mesa B

SURFACE HOLE FOOTAGE:

190'/S & 2180'/E

BOTTOM HOLE FOOTAGE

330'/N & 2180'/E

LOCATION:

Sec. 7, T. 26 S., R. 33 E.

COUNTY:


Lea County, New Mexico

All previous COAs still apply except the following:

A. PRESSURE CONTROL

- 1. Variance approved to use flex line from BOP to choke manifold. Check condition of flexible line from BOP to choke manifold, replace if exterior is damaged or if line fails test. Line to be as straight as possible with no hard bends and is to be anchored according to Manufacturer's requirements. The flexible hose can be exchanged with a hose of equal size and equal or greater pressure rating. Anchor requirements, specification sheet and hydrostatic pressure test certification matching the hose in service, to be onsite for review. These documents shall be posted in the company man's trailer and on the rig floor. If the BLM inspector questions the straightness of the hose, a BLM engineer will be contacted and will review in the field or via picture supplied by inspector to determine if changes are required (operator shall expect delays if this occurs).
- 2. Operator has proposed a multi-bowl wellhead assembly. This assembly will only be tested when installed on the surface casing. Minimum working pressure of the blowout preventer (BOP) and related equipment (BOPE) required for drilling below the surface casing shoe shall be 3000 (3M) psi.
 - a. Wellhead shall be installed by manufacturer's representatives, submit documentation with subsequent sundry.
 - b. If the welding is performed by a third party, the manufacturer's representative shall monitor the temperature to verify that it does not exceed the maximum temperature of the seal.
 - c. Manufacturer representative shall install the test plug for the initial BOP test.
 - d. Operator shall perform the intermediate casing integrity test to 70% of the casing burst. This will test the multi-bowl seals.
 - e. If the cement does not circulate and one inch operations would have been possible with a standard wellhead, the well head shall be cut off, cementing operations performed and another wellhead installed.

NOTE: THIS DRAWING IS NOT TO SCALE. THE DIMENSIONS REFLECTED ON THIS DRAWING ARE ESTIMATED DIMENSIONS AND ARE FOR REFERENCE ONLY.





© 2016 Weatherford All rights reserved

Customer:	BTA OIL PRODUCERS	Project No.: 146245	Quote No.:	291545 v2
Project Name:	WEST TEXAS	Date: 07/06/16	Drawn By:	JL



COMPLICAL

CONTITECH RUBBER Industrial Kft.

No:QC-DB- 599/ 2014

Page: 16 / 176

QUALITY CONTROL CERT No: 1592 INSPECTION AND TEST CERTIFICATE ContiTech Oil & Marine Corp. 4500461753 PURCHASER: P.O. Nº: Choke & Kill Hose 539225 3" ID CONTITECH ORDER N HOSE TYPE: 68547 7.62 m / 7.66 m HOSE SERIAL Nº NOMINAL / ACTUAL LENGTH: min. 68,9 10000 T.P. 103,4 MPa psi Duration: 60 15000 Pressure test with water at ambient temperature See attachment. (1 page) 10 Min. 50 MPa COUPLINGS Type Serial No Quality · Heat No A1582N H8672 3" coupling with 2574 5533 AISI 4130 4 1/16" 10K API Swivel Flange end 58855 AISI 4130 A1199N A1423N Hub AISI 4130 Not Designed For Well Testing API Spec 16 C Fire Rated Temperature rate:"B" All metal parts are flawless WE CERTIFY THAT THE ABOVE HOSE HAS BEEN MANUFACTURED IN ACCORDANCE WITH THE TERMS OF THE ORDER INSPECTED AND PRESSURE TESTED AS ABOVE WITH SATISFACTORY RESULT. STATEMENT OF CONFORMILY: We hareby certify that the above items/equipment supplied by us are in conformity with the terms. conditions and specifications of the above Purchaser Order and that these items/equipment were labricated inspected and tested in accordance with the referenced standards, codes and specifications and meet the relevant accoptance criteria and design requirements Date: Inspector Quality Control influential life. 04 September 2014. cellity Control Tic

11-

File Name File Massage Device Type Senal No. Data Count

. 000220_68543,68545+547.GEV.....000236_68543,66546+547.GEV 68543,68545,88547 : GX10 : SSP606399 - 9946


Sampling Inc. Start Time Stop Time

1.000 sec 2014/09/04 01:53:54:000 2014/09/04 04:09:39:000

Print Group Print Range Common!

Press-Temp . 2014/09/04 01:53:54 000 - 2014/09/04 04:39:39.000

Cursor B Difference Cursor A Data No. 7032 3600 2014/09/04 2014(03/04 Absolute Time 01 00:00:000 Tog Comment Value A Value B Vatue 3-4 1048.57 -14.39 Pressure[bor] 1002.03 23.14 Ambient Temperatura (*C) 23.24 -0.10



Page: 1/1

10min(d)v