Submit One Copy To Appropriate District State of New Mexico	Form C-103		
District I 1625 N. French Dr., Hobbs, NM 88240	Revised November 3, 2011 WELL API NO.		
District II 811 S. First St., Artesia Strue 88219 2016 OIL CONSERVATION DIVISION	30-025-24164 5. Indicate Type of Lease		
District III 1220 South St. Francis Dr.	STATE STATE STATE		
1000 Rio Brazos Rd., Aztec, NM 87410 ED District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
District IV 1220 S. St. Francis Dr. Francis Dr. NM 87505	1149417		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Warrior State		
1. Type of Well: Oil Well Gas Well Other	8. Well Number 2		
2. Name of Operator Finley Resources Inc.	9. OGRID Number 180387		
3. Address of Operator	10. Pool name or Wildcat		
1308 Lake Street, Ft Worth, TX 76102	Eumont: Vates - 7 Rivers - Queen		
4. Well Location	E		
Unit Letter <u>6</u> : 4545 feet from the <u>N</u> line and <u>1980</u> feet from the			
Section <u>02</u> Township <u>21S</u> Range <u>35E</u> NMPM County <u>L</u>			
11. Elevation (Show whether DR, RKB, RT, GR, etc. 3583 GL			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other D	Data		
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A			
PULL OR ALTER CASING			
OTHER: 🔲 🛛 Location is r	eady for OCD inspection after P&A		
All pits have been remediated in compliance with OCD rules and the terms of the Ope			
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been	properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in	n concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QU	LARTER/OUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATIO			
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.			
The location has been leveled as nearly as possible to original ground contour and has other production equipment.	been cleared of all junk, trash, flow lines and		
Anchors, dead men, tie downs and risers have been cut off at least two feet below grou	und level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s			
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, proc from lease and well location.	luction equipment and junk have been removed		
All metal bolts and other materials have been removed. Portable bases have been removed.	oved. (Poured onsite concrete bases do not have		
to be removed.)			
All other environmental concerns have been addressed as per OCD rules.			
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC	. All fluids have been removed from non-		
retrieved flow lines and pipelines. If this is a one-well lease or last remaining well on lease: all electrical service poles an	d lines have been removed from lease and well		
location, except for utility's distribution infrastructure.	a mes have been removed from lease and wen		
When all work has been completed, return this form to the appropriate District office to sch	nedule an inspection.		
SIGNATURE AL TITLE Regulatory Anal	Ust DATE 9/26/16		
	/ / /		
TYPE OR PRINT NAME Osh Morgan E-MAIL: jmorgan@finley For State Use Only	DATE 10/5/2016		
LUI CHURCH DE CHINE	- I-bal		
APPROVED BY: Machentatan TITLE P.E.S.	DATE 1015/2016		

DATE	10	15/	201	6
DILLE			_	