Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
The state of the s	Energy, Minerals and Natural Resources  OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505  ICES AND REPORTS ON WELLS	Revised August 1, 2011  WELL API NO.  30-005-60810  5. Indicate Type of Lease STATE FEE X  6. State Oil & Gas Lease No.  7. Lease Name or Unit Agreement Name
	SALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A CATION FOR PERMIT" (FORM C-101) FOR SUCH  Gas Well Other	Twin Lakes San Andres Unit  8. Well Number 51
Name of Operator     State of New Mexico formerly	Canyon E&P Company	9. OGRID Number
Address of Operator     811 South 1 <sup>st</sup> Street Artesia, N     Well Location	M 88210	10. Pool name or Wildcat Twin Lakes, San Andres (Assoc)
Section 31	Township 8S Range 29E  11. Elevation (Show whether DR, RKB, RT, GR, etc.)  Appropriate Box to Indicate Nature of Notice	
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	INT TO PA REMEDIAL WO	RILLING OPNS. □ P AND A XX
OTHER:	OTHER:	
	oleted operations. (Clearly state all pertinent details, a bork). SEE RULE 19.15.7.14 NMAC. For Multiple Completion.  SEE ATTACHED	Ompletions: Attach wellbore diagram of Selven Selve
		SBS OCD
I hereby certify that the information	above is true and complete to the best of my knowled	ge and belief.
SIGNATURE Wallet		r. Specialist DATE 10/3/2016
Type or print name Mark u For State Use Only	0	575 PHONE: 393-6161
APPROVED BY: Conditions of Approval (if any):	Thrown TITLE Dist, Supe	WUSOL DATE 10/5/2016

## Plugging Report TLSAU #51

8/26/2016 Moved in rig and equipment. Installed 1 temporary anchor. Rigged up and dug out cellar. Installed BOP. No pipe in the well. Used pipe trailer move 58 joints from the #21 & 36 joints from the #13 well to use as work string.

8/29/2016 Casing was standing full of fluid. RIH with gauge ring and set down @ 2620'. RIH with tubing to 2697' and circulated MLF and spotted 45 sx Class C cement. WOC and tagged cement at 2068'. Closed BOP and tested casing to 500#. Held good. Perforated 4 ½' casing at 1000'. RIH with packer and set at 704'. Established rate into perfs. Squeezed perfs with 35 sx cement. No circulation to the pit. WOC 3 hrs. Still had 400# on tubing. Would not bleed off. Cement still not set up. Left packer set and SION

8/30/2016 RIH and tagged cement at 823'. Perforated casing at 176'. Established circulation and pumped cement down 4 ½" casing to perfs at 176' and up annulus to surface. Took 65 sx cement to get cement to surface. Shut down for thunderstorm.

9/5/2016 Rigged down and cut off wellhead. Filled up both strings with 10 sx cement. Installed marker and cut off anchors. Cleaned pit and cleared location.