

State of New Mexico
Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Tony Delfin
Acting Cabinet Secretary

David Catanach, Director
Oil Conservation Division



Response Required - Deadline Enclosed

*Field Inspection Program
"Preserving the Integrity of Our Environment"*

27-Oct-16

CROSS BORDER RESOURCES, INC.
14282 GILLIS RD
FARMERS BRANCH TX 75244

HOBBS OCD
OCT 27 2016
RECEIVED

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.


Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

LOVELESS SWD No.005				D-36-7S-31E	30-005-20828-00-00	
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
10/27/2016	Routine/Periodic	Mark Whitaker	Yes	No	11/30/2016	iMAW1630129799
	Violations					
	Surface Damage/Restoration					
Comments on Inspection:		DO NOT RELEASE. Pile of conduit, chemical drum and other debris on south side. Mounds of contaminated soil and caliche on west side. Wellhead and concrete blocks on north side. Depression at wellhead site. NEED TO REMOVE PILE OF DEBRIS FROM SOUTH SIDE OF LOCATION, NEED TO REMOVE AND PROPERLY DISPOSE OF CONTAMINATED SOIL AND CALICHE FROM WEST SIDE OF LOCATION, NEED TO REMOVE CUTOFF WELLHEAD AND CONCRETE FROM NORTH SIDE OF LOCATION, AND FILL IN DEPRESSION AT WELLHEAD SITE ON NORTHEAST CORNER. 1ST NOTICE.				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,


Petroleum Engr. Specialist

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER

FIRST-CLASS MAIL

\$000.46⁵

10/27/2016 ZIP 88240
012E14642224

US POSTAGE

CROSS BORDER RESOURCES, INC.
14282 GILLIS RD
FARMERS BRANCH, TX 75244